INSPECTION REPORT



For the Property at: 127 JACKSON WAY NORTHAMPTON, MA 01060

Prepared for: JANE BROWN Inspection Date: Friday, March 20, 2015 Prepared by: Edward Hamel



Hamel Inspections, LLC 155 Glendale Rd Southampton, MA 01073 413 244 2343

hamelinspections@gmail.com

An evaluation and professional opinion of the performance of the readily accessible installed systems in a home.



October 13, 2015

Dear Jane Brown,

RE: Report No. 1004, v.3 127 Jackson Way Northampton, MA 01060

Thank you for choosing us to perform your Home Inspection. We trust the experience was both useful and enjoyable.

Please feel free to call with any questions you may have regarding the report.

Thanks again for allowing us to work with you.

Sincerely,

Edward Hamel on behalf of Hamel Inspections, LLC

> Hamel Inspections, LLC 155 Glendale Rd Southampton, MA 01073 413 244 2343

hamelinspections@gmail.com



INVOICE

October 13, 2015

Client: Jane Brown

Report No. 1004, v.3 For inspection at: 127 Jackson Way Northampton, MA 01060 on: Friday, March 20, 2015

Home inspection

\$450.00

Total

\$450.00

PAID IN FULL - THANK YOU!

Hamel Inspections, LLC 155 Glendale Rd Southampton, MA 01073 413 244 2343

hamelinspections@gmail.com

PARTIES TO THE AGREEMENT

Company Hamel Inspections, LLC 155 Glendale Rd Southampton, MA 01073 Client Jane Brown 127 Jackson Way Northampton, MA

Total Fee: \$450.00

This is an agreement between Jane Brown and Hamel Inspections, LLC.

Hamel Home Inspections

Inspection Agreement

This is an agreement between the above listed Client and Hamel Home inspections. The client requests that Hamel Home Inspections conduct a home inspection at the above listed address. and prepare a home inspection report. The client warrants that permission has been obtained from the owner to conduct an inspection of the property.

The client agrees to pay the agreed upon fee at the conclusion of the on site inspection.

Hamel Home Inspections agrees to perform the inspection in accordance with the Massachusetts Standards of Practice, <u>http://www.mass.gov/ocabr/licensee/dpl-boards/hi/266-cmr-600.html</u> The client understands that these standards contain limitations, exceptions, and exclusions. A home inspection is an in-field evaluation and professional opinion of the performance of the readily accessible and installed systems in a home at one point in time.

A standard home inspection is a visual examination of the physical structure and major interior systems of a residential building consisting of one to four dwelling units. It should be understood that there are certain risks inherent in the purchase of property and a home inspection is inherently limited in its scope and depth. A home inspection will not identify concealed defects nor is it intended to predict future performance or life expectancy. The information gained from this home inspection may reduce some risks but is not intended to provide the client with protection from all risks involved. It should be clearly understood that a home inspection is not to be confused with an appraisal, a building code inspection, a guarantee of any kind, and/or an insurance policy on the condition of the property.

Home inspectors will not find conditions that may be only visible when storage or furniture is moved. We do not remove wall coverings, lift flooring, including carpet, or move storage to look underneath or behind.

Please carefully read the exclusions set forth in the MA Standards. Home inspectors are not required to inspect environmental conditions, subterranean soil conditions, insect infestation, lead paint, radon, mold or mildew, asbestos, septic systems, buried tanks, urea formaldehyde and drywall manufactured in China. Homeowners may want to consider a complete environmental evaluation of the property before buying. It can be impossible to observe water/moisture, leaks, seepage and drainage problems, unless the inspection is conducted during or immediately following rain sufficient to reveal such problems. This property inspection is performed for the sole use of the client. It may not be transferred or assigned to any third party. Hamel Inspections accepts no responsibility for use by any third party.

As a courtesy, we may exceed the MA Standards in a particular area but should not be expected to exceed requirements in other areas. Any comments made during the inspection that go beyond the MA Standards should be considered gratuitous in nature. It should be clearly understood that a home inspection is not to be confused with an appraisal, a building code inspection, a guarantee of any kind, and/or an insurance policy on the condition of the property.

| I, (print | it), (signature), |
|-----------|---|
| (date)_ | , have read, understood and accepted the terms of this agreement. |

| I, Jane Brown (Signature) | , (Date) | , have read, understood and |
|---------------------------------------|----------|-----------------------------|
| accepted the terms of this agreement. | | |

127 Jackson Way, Northampton, MA March 20, 2015

| SUMMARY | ROOFING | EXTERIOR | STRUCTURE | ELECTRICAL | HEATING | INSULATION | PLUMBING | INTERIOR | SITE INFO |
|----------|-----------|----------|-----------|------------|---------|------------|----------|----------|-----------|
| APPENDIX | REFERENCE | | | | | | | | |
| | | | | | | | | | |

This Summary outlines potentially significant issues from a cost or safety standpoint. This section is provided as a courtesy and cannot be considered a substitute for reading the entire report. Please read the complete document. <u>Priority Maintenance Items</u>

Roofing

SLOPED ROOFING \ Composition shingles

Condition: • Near end of life expectancy

There is excessive growth of moss and lichens on the north side of the roof that is shortening the life of the shingles. **Task**: Monitor

Condition: • <u>Cupping, curling, clawing</u> Task: Monitor

Condition: • <u>Slots wide</u> Task: Monitor

Exterior

ROOF DRAINAGE \ Gutters

Condition: • Discharging onto roof Location: Second Floor Porch Task: Monitor

ROOF DRAINAGE \ Downspouts

Condition: • <u>Downspouts end too close to building</u> Task: Improve

WALLS \ Trim

Condition: • Rot or insect damage

There is decay where the siding is close to the ground near gas entrance. The decay goes through the siding into the sill.

Location: Rear Exterior Task: Repair Time: Immediate

WALLS \ Wood siding

Condition: • <u>Cracked, split or broken</u> There is cracking at various locations on the north and south sides Location: Various Task: Repair

EXTERIOR GLASS \ Glass (glazing)

Condition: • Putty missing, cracked or deteriorated. **Location**: Various

127 Jackson Way, Northampton, MA March 20, 2015

| SUMMARY | ROOFING | EXTERIOR | STRUCTURE | ELECTRICAL | HEATING | INSULATION | PLUMBING | INTERIOR | SITE INFO |
|---------|---------|----------|-----------|------------|---------|------------|----------|----------|-----------|
| | | | | | | | | | |

APPENDIX REFERENCE

Task: Repair

DOORS \ Exterior trim

Condition: • The two porch doors are not opening and closing well. Location: Porch Task: Repair

PORCHES, DECKS, STEPS, PATIOS AND BALCONIES \ Joists

Condition: • The steel posts supporting the side porch could not be inspected because of no access. These posts are prone to decay from rust.
 Location: Left Porch
 Task: Monitor, further evaluation

Condition: • Fastener problems

The porch floor may be pulling away from the house. Location: Left Side Porch Task: Monitor

PORCHES, DECKS, STEPS, PATIOS AND BALCONIES \ Steps and landings

Condition: • Trip hazard
The exterior stairs are uneven and broken in places. This is a trip hazard. Handrails need to be installed.
Implication(s): Trip or fall hazard
Location: Front and side
Task: Provide

PORCHES, DECKS, STEPS, PATIOS AND BALCONIES \ Handrails and guards

Condition: • <u>Missing</u> Implication(s): Fall hazard Task: Provide

LANDSCAPING \ Lot grading

Condition: • <u>Improper slope</u> grade here is minimal, potential for water to come into home. **Location**: Rear

LANDSCAPING \ Driveway

Condition: • <u>Cracked or damaged surfaces</u> There are a couple of long cracks to be repaired at the driveway. **Task**: repair

| 127 Jackson Way, Nor | hampton, MA | 1arch 20, 2015 | | | | | |
|---|----------------------|------------------------|---------------|------------|----------|----------|-----------|
| SUMMARY ROOFING | EXTERIOR STRU | CTURE ELECTRICAL | HEATING | INSULATION | PLUMBING | INTERIOR | SITE INFO |
| APPENDIX REFERENCE | | | | | | | |
| Structure | | | | | | | |
| FOUNDATIONS \ Four Condition: • Mortar de Task: Repair | | ing | | | | | |
| FLOORS \ Joists Condition: • Rot Thee is some decay ha Location: Various Bas Task: Monitor, repair | | s locations of joists, | sills, and be | eams. | | | |
| FLOORS \ Concrete s Condition: • There is s Task: Improve | | s, possible trip haz | ard. | | | | |
| ROOF FRAMING \ Col Condition: • Missing Location: Throughout Task: Provide | lar ties/rafter ties | <u>i</u> | | | | | |
| Electrical | | | | | | | |
| SERVICE BOX, GROU Condition: • Damaged door is not mounted Task: Provide | | • | <u>panel</u> | | | | |
| Condition: • Openings Location: Basement Task: repair | <u>; in panel</u> | | | | | | |
| Condition: • <u>Double ta</u> Task: Repair | 1 <u>ps</u> | | | | | | |
| DISTRIBUTION SYST Condition: • Not well a service line to outside r Location: Basement Task: Improve Time: Discretionary | secured | | | | | | |
| DISTRIBUTION SYST Condition: • No GFI (Location: Laundry Are Task: Provide | Ground Fault Interr | • • | | | | | |

| 127 Jackson Way, Nort | hampton, MA | March 2 | 20, 2015 | | | | | |
|---|-----------------------|--------------------|------------------|-------------|-----------------|-------------|----------|-----------|
| SUMMARY ROOFING | EXTERIOR | STRUCTURE | ELECTRICAL | HEATING | INSULATION | PLUMBING | INTERIOR | SITE INFO |
| APPENDIX REFERENCE | | | | | | | | |
| | | | | | | | | |
| Condition: • GFI test f | <u>aulty</u> | | | | | | | |
| Location: Kitchen | | | | | | | | |
| Task: Repair | | | | | | | | |
| Time: Immediate | | | | | | | | |
| | | | | | | | | |
| Heating | | | | | | | | |
| | | | | | | | | |
| <u>General</u> | | | 4 | | | | | |
| Gas fired heating plan | its should be | serviced ev | ery other yea | ar and upon | i moving into t | ne new nome | 9 | |
| Task: Service | | | | | | | | |
| GAS FURNACE \ Duct | <u>s, registers</u> : | and grilles | | | | | | |
| Condition: • Duct exte | nsions not we | ell connecte | d to main tru | ınk. | | | | |
| Task: repair | | | | | | | | |
| Condition: • Weak airf | low | | | | | | | |
| Location: Various | <u>10w</u> | | | | | | | |
| Task: improve | | | | | | | | |
| rusk. improve | | | | | | | | |
| Condition: • Excessive | <u>ely long runs,</u> | excessive | <u>elbows</u> | | | | | |
| Location: Various | | | | | | | | |
| Task: improve | | | | | | | | |
| Condition: • Insulation | missing dar | naged | | | | | | |
| At ductwork | | | | | | | | |
| Location: Basement | | | | | | | | |
| Task: improve | | | | | | | | |
| Condition. Missing | | | | | | | | |
| Condition: • Missing There is no cold return | air ducte on e | econd floor | | | | | | |
| Location: Second Floo | | | | | | | | |
| Task: Monitor, improve | | | | | | | | |
| | | | | | | | | |
| GAS FURNACE \ Mid- | - | <u>iiciency ga</u> | <u>s furnace</u> | | | | | |
| Condition: • Condensa | | | | | | | | |
| condensate pipe goes i | nto ground. | | | | | | | |
| Location: Basement | | | | | | | | |
| Task: Monitor | | | | | | | | |
| WOOD STOVE \ Cabin | <u>iet, door and</u> | l clearance | <u>S</u> | | | | | |
| Condition: • Floor - co | mbustible cle | arance inac | <u>dequate</u> | | | | | |
| Location: First Floor | | | | | | | | |
| Task: Repair | | | | | | | | |
| Time: Immediate | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |

127 Jackson Way, Northampton, MA March 20, 2015

| 127 Jackson Wa | ay, North | ampton, MA | A March 2 | 20, 2015 | | | | | |
|-----------------------|-------------|----------------|--------------|----------------|---------|---------------|----------------|---------------|-----------|
| SUMMARY RO | OFING | EXTERIOR | STRUCTURE | ELECTRICAL | HEATING | INSULATION | PLUMBING | INTERIOR | SITE INFO |
| APPENDIX REFE | ERENCE | | | | | | | | |
| AFPENDIA REFE | IRENCE | | | | | | | | |
| WOOD STOVE | \ Ventir | <u>ig</u> | | | | | | | |
| Condition: • R | ust or ob | structed | | | | | | | |
| There is rust wh | here the | exhaust pipe | meets the | stove. | | | | | |
| Location: First | Floor | | | | | | | | |
| Task: Replace | | | | | | | | | |
| Time: Immediat | ie | | | | | | | | |
| | | | • | | | | | | |
| CHIMNEY AND | | - | - | | | | | | |
| Condition: • Lo | | - | riorated ma | <u>sonry</u> | | | | | |
| In the top 3' of t | | iey | | | | | | | |
| Location: Rear | | | | | | | | | |
| Task: Repair | | | | | | | | | |
| Condition: • S | palling | | | | | | | | |
| Location: Rear | | | | | | | | | |
| Task: Repair | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| Insulation a | ind Ve | ntilation | | | | | | | |
| | In a colat: | | | | | | | | |
| ATTIC/ROOF \ | | | | | | | | | |
| Condition: • <u>A</u> | | | ent standard | <u>15</u> | | | | | |
| Task: Further e | valuation | 1 | | | | | | | |
| ATTIC/ROOF \ | Attic st | aircase | | | | | | | |
| Condition: • H | | | missing or | unsafe | | | | | |
| guard rails could | | - | | unsale | | | | | |
| Implication(s): | • | | | | | | | | |
| Location: First | • | | \ ++io | | | | | | |
| | F1001 36 | | AUIC | | | | | | |
| Task: Improve | | | | | | | | | |
| FOUNDATION | \Interio | r insulation | | | | | | | |
| Condition: • N | | | | | | | | | |
| Some could be | | t the box sill | | | | | | | |
| Task: Improve | | | | | | | | | |
| r - · - | | | | | | | | | |
| Dhumhing | | | | | | | | | |
| Plumbing | | | | | | | | | |
| WASTE PLUMI | | rain nining | - nerforma | nce | | | | | |
| Condition: • Le | | | | | | | | | |
| | | the cast iron | soil pipe or | it avite tha h | ome The | foundation bo | le for the coi | l nine should | l he |
| There is a small | i ieak al | ine cast ii011 | soli pipe as | | | iounuation no | | i hihe suodic | |
| repaired. | mont | | | | | | | | |
| Location: Base | ment | | | | | | | | |
| Task: Improve | | | | | | | | | |
| Time: Discretion | narv | | | | | | | | |

Time: Discretionary

| 127 Jackson Way, Nort | hampton, MA | 1arch 20, 2015 | | | | | |
|---|---------------------|------------------|---------|------------|----------|----------|-----------|
| SUMMARY ROOFING | EXTERIOR STRU | CTURE ELECTRICAL | HEATING | INSULATION | PLUMBING | INTERIOR | SITE INFO |
| APPENDIX REFERENCE | | | | | | | |
| FIXTURES AND FAUC Condition: • Loose Location: Second Floo Task: Repair | | | | | | | |
| FIXTURES AND FAUC Condition: • <u>Slow drain</u> Task: Improve | | | | | | | |
| Interior | | | | | | | |
| FLOORS \ General Condition: • Trip hazar Floor transition level is t Location: First Floor Ki Task: Monitor | uneven between s | some rooms | | | | | |
| FLOORS \ Resilient flo Condition: • Edges are Location: Second Floo Task: repair | e lifting. | | | | | | |
| FLOORS \ Subflooring Condition: • Springy Location: First Floor Se | - | | | | | | |
| FLOORS \ Concrete fle Condition: • uneven fle Location: Basement Task: Monitor, repair Time: Discretionary | | | | | | | |
| CEILINGS \ General Condition: • Typical fla Location: Various Task: Monitor | 3WS | | | | | | |
| WINDOWS \ Glass (gla Condition: • Lost seal Skylight Location: Second Floo | on double or triple | e glazing | | | | | |
| WINDOWS \ Skylight Condition: • Leak Thee are water stains o Location: Second Floo | | | | | | | |

| SUMMARY ROOFING | | STRUCTURE | ELECTRICAL | HEATING | INSULATION | PLUMBING | INTERIOR | SITE INFO |
|--|-----------------------------|---------------|------------|---------|------------|----------|----------|-----------|
| APPENDIX REFERENCE | | | | | | | | |
| Task: Monitor | | | | | | | | |
| DOORS \ Doors and fra Condition: • Does not I door knob at closet need Location: Rear Second Task: Repair Time: Discretionary | latch properly ds repair | | | | | | | |
| CARPENTRY \ Cabiner Condition: • Defective At sink base Location: Kitchen Task: Improve | | | | | | | | |
| STAIRS \ General Condition: • Poor lighti Implication(s): Trip or f Location: Various Base Task: Improve | all hazard | loor Second | Floor | | | | | |
| STAIRS \ Height Condition: • Cellar stai Task: Monitor | rway ceiling | height is low | , | | | | | |
| STAIRS \ Stringers Condition: • Rot at both The bottom stair tread s Location: Basement Task: repair | | laced. | | | | | | |
| STAIRS \ Handrails Condition: • <u>Too high</u> It is hard to hold Location: Basement Task: Improve | | | | | | | | |
| STAIRS \ Guardrails Condition: • Should be Task: Provide | improved in | both attics. | | | | | | |
| Condition: • <u>Too low</u> Implication(s): Fall haz Location: first floor attic Task: improve | | | | | | | | |
| | | | | | | | | |

| 127 Jacks | son Way, Nor | thampton, M | A March 2 | 20, 2015 | | | | | |
|------------------------|--|----------------|-------------------|-------------|-----------|--------------------------|---------------|--------------|-----------|
| SUMMARY | ROOFING | EXTERIOR | STRUCTURE | ELECTRICAL | HEATING | INSULATION | PLUMBING | INTERIOR | SITE INFO |
| APPENDIX | REFERENCE | | | | | | | | |
| Implicatio | n: • <u>Missing</u> on(s): Fall ha: : second floor wide | | | | | | | | |
| Conditio | NT ∖ Wet bas n: • <u>Water on</u> : Basement nitor | | <u>dence</u> | | | | | | |
| | NT \ Wet bas | | | ion noted | | | | | |
| Conditio | n: • <u>Dehumid</u> | ifier in baser | nent | | | | | | |
| | n: • <u>Periphera</u> : Throughout | | | | | | | | |
| Conditio | T FANS \ Ext n: • <u>Weather</u> : Rear Exterio pair | hood missin | <u>g or loose</u> | | | | | | |
| | n: • <u>Not vente</u> : Second Floc prove | | : | | | | | | |
| Condition Should be | : First Floor La place | - | | | | | | | |
| This conc | ludes the Sur | nmary sectio | on. | | | | | | |
| | inder of the re ents. Limitatio | - | | - | | also details an well. | ny recommen | dations we h | nave for |
| The suga | ested time fra | mes for com | pleting recor | nmendations | are based | on the limited | information a | available du | ring a |

The suggested time frames for completing recommendations are based on the limited information available during a pre-purchase home inspection. These may have to be adjusted based on the findings of specialists.

Home Improvement - ballpark costs

ROOFING

127 Jackson Way, Northampton, MA March 20, 2015

| SUMMARY | ROOFING | EXTERIOR | STRUCTURE | ELECTRICAL | HEATING | INSULATION | PLUMBING | INTERIOR | SITE INFO |
|----------|------------|----------|-----------|------------|---------|------------|----------|----------|-----------|
| APPENDIX | REFERENCE | | | | | | | | |
| Descrip | otion | | | | | | | | |
| General: | Roof Penet | rations. | | | | | | | |

Note: There are two plumbing vents, one roof antennae, one chimney and one skylight.

Sloped roofing material: • Composition shingles

Sloped roof flashing material: • Aluminum • Copper

Limitations

Inspection performed: • Looking out house window

Inspection performed: • By walking on roof • With binoculars from the ground

Recommendations

SLOPED ROOFING \ Composition shingles

1. Condition: • <u>Near end of life expectancy</u>

There is excessive growth of moss and lichens on the north side of the roof that is shortening the life of the shingles. **Task**: Monitor

2. Condition: • <u>Cupping, curling, clawing</u> Task: Monitor

3. Condition: • <u>Slots wide</u>

Task: Monitor

127 Jackson Way, Northampton, MA March 20, 2015

| SUMMARY | ROOFING | EXTERIOR | STRUCTURE | ELECTRICAL | HEATING | INSULATION | PLUMBING | INTERIOR | SITE INFO |
|----------|-----------|----------|-----------|------------|---------|------------|----------|----------|-----------|
| APPENDIX | REFERENCE | | | | | | | | |
| Decerin | 4.00 | | | | | | | | |

Description

Gutter & downspout material:

<u>Aluminum</u>

gutter missing on back side of side entrance building and only partial at front of building low roof area. There are no gutters on the left side porch



1. Aluminum

Gutter & downspout discharge:
• <u>Above grade</u>

Lot slope: • Away from building • Towards building

Wall surfaces: • Wood • clapboards

Soffit and fascia: • Wood

Driveway: • Blacktop

Walkway: • There is no walkway other than grass to 3 doors.

Porch: • Wood

Exterior steps: • Concrete • Stone

Limitations

No or limited access to: • Area below steps, deck, porches

Recommendations

ROOF DRAINAGE \ Gutters

4. Condition: • Discharging onto roof
 Location: Second Floor Porch
 Task: Monitor

ROOF DRAINAGE \ Downspouts


5. Condition: • <u>Downspouts end too close to building</u> Task: Improve

Setting the standard for quality home inspections.

Page 10 of 58

127 Jackson Way, Northampton, MA March 20, 2015

| SUMMARY | ROOFING | EXTERIOR | STRUCTURE | ELECTRICAL | HEATING | INSULATION | PLUMBING | INTERIOR | SITE INFO |
|----------|-----------|----------|-----------|------------|---------|------------|----------|----------|-----------|
| APPENDIX | REFERENCE | | | | | | | | |



WALLS \ Trim

6. Condition: • Rot or insect damage

There is decay where the siding is close to the ground near gas entrance. The decay goes through the siding into the sill.

Location: Rear Exterior Task: Repair Time: Immediate

127 Jackson Way, Northampton, MA March 20, 2015

| SUMMARY | ROOFING | EXTERIOR | STRUCTURE | ELECTRICAL | HEATING | INSULATION | PLUMBING | INTERIOR | SITE INFO | |
|----------|-----------|----------|-----------|------------|---------|------------|----------|----------|-----------|--|
| APPENDIX | REFERENCE | | | | | | | | | |
| | | | | | | | | | | |



2. Rot or insect damage

WALLS \ Wood siding

7. Condition: • <u>Cracked, split or broken</u>
There is cracking at various locations on the north and south sides
Location: Various

Task: Repair



3. Cracked, split or broken

EXTERIOR GLASS \ Glass (glazing)

8. Condition: • Putty missing, cracked or deteriorated.

Setting the standard for quality home inspections.

| EXTERIOR | Report No. 1004, v.3 |
|---|----------------------|
| 127 Jackson Way, Northampton, MA March 20, 2015 | |
| SUMMARY ROOFING EXTERIOR STRUCTURE ELECTRICAL HEATING INSULATION PLUMBING | INTERIOR SITE INFO |
| APPENDIX REFERENCE | |
| Location: Various | |
| Task: Repair | |
| DOORS \ Exterior trim | |
| 9. Condition: • The two porch doors are not opening and closing well. | |
| Location: Porch | |
| Task: Repair | |
| | |
| 10. Condition: • The Exterior doors have double cylinders. This could be a serious safety issue. | |
| Location: Throughout | |
| Task: Improve | |
| Time: Immediate | |
| BASEMENT ENTRANCES \ Basement stairwells | |
| 11. Condition: • Step and landing problems | |
| There is no door, only a pressure treated plywood cover. The stairs under the plywood are unever | n and a trip hazard. |
| Implication(s): Trip or fall hazard | |
| Location: Basement | |
| Task: Upgrade | |
| | |
| PORCHES, DECKS, STEPS, PATIOS AND BALCONIES \ Joists | |
| 12. Condition: • The steel posts supporting the side porch could not be inspected because of no | access These posts |

12. Condition: • The steel posts supporting the side porch could not be inspected because of no access. These posts are prone to decay from rust. Location: Left Porch Task: Monitor, further evaluation

13. Condition: • Fastener problems The porch floor may be pulling away from the house. Location: Left Side Porch Task: Monitor

PORCHES, DECKS, STEPS, PATIOS AND BALCONIES \ Steps and landings

14. Condition: • Trip hazard The exterior stairs are uneven and broken in places. This is a trip hazard. Handrails need to be installed. Implication(s): Trip or fall hazard Location: Front and side Task: Provide

127 Jackson Way, Northampton, MA March 20, 2015

| SUMMARY | ROOFING | EXTERIOR | STRUCTURE | ELECTRICAL | HEATING | INSULATION | PLUMBING | INTERIOR | SITE INFO |
|----------|-----------|----------|-----------|------------|---------|------------|----------|----------|-----------|
| APPENDIX | REFERENCE | | | | | | | | |





4. Step and landing problems

5. Step and landing problems

PORCHES, DECKS, STEPS, PATIOS AND BALCONIES \ Handrails and guards

15. Condition: • <u>Missing</u> **Implication(s)**: Fall hazard **Task**: Provide

LANDSCAPING \ Lot grading

16. Condition: • <u>Improper slope</u> grade here is minimal, potential for water to come into home. **Location**: Rear

LANDSCAPING \ Driveway

17. Condition: • <u>Cracked or damaged surfaces</u>There are a couple of long cracks to be repaired at the driveway.**Task**: repair

LANDSCAPING \ General

18. Condition: • Shrubs are too close to building.

STRUCTURE

| 127 Jackson Way, Northampton, MA March 20, 2015 | |
|--|--------------------|
| SUMMARY ROOFING EXTERIOR STRUCTURE ELECTRICAL HEATING INSULATION PLUMBING | INTERIOR SITE INFO |
| APPENDIX REFERENCE | |
| Description | |
| Configuration: | |
| • <u>Basement</u> | |
| • <u>Slab-on-grade</u> Electric out of level with trip hereards. There is a built in drain system into the floor. | |
| Floor is out of level with trip hazards. There is a built in drain system into the floor. | |
| Foundation material: • <u>Stone</u> • <u>Brick</u> | |
| Floor construction: | |
| • <u>Joists</u> • Wood columns | |
| Some of the wood columns appear to be temporary and could be replaced. | |
| Masonry columns | |
| Wood beams | |
| • Subfloor - plank | |
| Exterior wall construction: • Wood frame • Post and beam | |
| Roof and ceiling framing: • Electric attic light | |
| <i>Note:</i> There are lights in each of 2 attics. | |
| Roof and ceiling framing: | |
| <u>Rafters/roof joists</u> <u>Plank sheathing</u> | |
| Plywood sheathing | |
| plywood was added over boards. | |
| | |
| | |
| Limitations | |
| Limitations Inspection limited/prevented by: | |
| Limitations Inspection limited/prevented by: • Storage | |
| Limitations Inspection limited/prevented by: | |
| Limitations Inspection limited/prevented by: • Storage 90% of the attic floors was covered with storage. Crawl space: | |
| Limitations Inspection limited/prevented by: • Storage 90% of the attic floors was covered with storage. Crawl space: • No access | |
| Limitations Inspection limited/prevented by: • Storage 90% of the attic floors was covered with storage. Crawl space: • No access At side porch. | |
| Limitations Inspection limited/prevented by: • Storage 90% of the attic floors was covered with storage. Crawl space: • No access | |
| Limitations Inspection limited/prevented by: • Storage 90% of the attic floors was covered with storage. Crawl space: • No access At side porch. Percent of foundation not visible: • 25 % | |
| Limitations Inspection limited/prevented by: • Storage 90% of the attic floors was covered with storage. Crawl space: • No access At side porch. | |
| Limitations Inspection limited/prevented by: • Storage 90% of the attic floors was covered with storage. Crawl space: • No access At side porch. Percent of foundation not visible: • 25 % Recommendations FOUNDATIONS \ Foundation | |
| Limitations Inspection limited/prevented by: • Storage 90% of the attic floors was covered with storage. Crawl space: • No access At side porch. Percent of foundation not visible: • 25 % Recommendations FOUNDATIONS \ Foundation 19. Condition: • Mortar deteriorating or missing | |
| Limitations Inspection limited/prevented by: • Storage 90% of the attic floors was covered with storage. Crawl space: • No access At side porch. Percent of foundation not visible: • 25 % Recommendations FOUNDATIONS \ Foundation | |
| Limitations Inspection limited/prevented by: • Storage 90% of the attic floors was covered with storage. Crawl space: • No access At side porch. Percent of foundation not visible: • 25 % Recommendations 19. Condition: • Mortar deteriorating or missing Task: Repair FLOORS\Joists | |
| Limitations Inspection limited/prevented by: • Storage 90% of the attic floors was covered with storage. Crawl space: • No access At side porch. Percent of foundation not visible: • 25 % Recommendations FOUNDATIONS \ Foundation 19. Condition: • Mortar deteriorating or missing Task: Repair FLOORS \ Joists 20. Condition: • Rot | |
| Limitations Inspection limited/prevented by: • Storage 90% of the attic floors was covered with storage. Crawl space: • No access At side porch. Percent of foundation not visible: • 25 % Recommendations FOUNDATIONS \ Foundation 19. Condition: • Mortar deteriorating or missing Task: Repair FLOORS \ Joists | |
| Limitations Inspection limited/prevented by: • Storage 90% of the attic floors was covered with storage. Crawl space: • No access At side porch. Percent of foundation not visible: • 25 % Recommendations FOUNDATIONS \ Foundation 19. Condition: • Mortar deteriorating or missing Task: Repair FLOORS \ Joists 20. Condition: • Rot | |

STRUCTURE

127 Jackson Way, Northampton, MA March 20, 2015

| SUMMARY | ROOFING | EXTERIOR | STRUCTURE | ELECTRICAL | HEATING | INSULATION | PLUMBING | INTERIOR | SITE INFO | |
|-----------|----------------------------|----------|-----------|------------|---------|------------|----------|----------|-----------|--|
| APPENDIX | REFERENCE | | | | | | | | | |
| Location: | Location: Various Basement | | | | | | | | | |

Task: Monitor, repair

FLOORS \ Concrete slabs

21. Condition: • There is some uneven areas, possible trip hazard. **Task**: Improve

ROOF FRAMING \ Collar ties/rafter ties

22. Condition: • Missing Location: Throughout Task: Provide

ELECTRICAL

127 Jackson Way, Northampton, MA March 20, 2015

| SUMMARY ROOFING EXTERIOR STRUCTURE ELECTRICAL HEATING INSULATION PLUMBING INTERIOR SITE INFO | | | | | | | | | | |
|---|--|--|--|--|--|--|--|--|--|--|
| APPENDIX REFERENCE | | | | | | | | | | |
| Description | | | | | | | | | | |
| Service entrance cable and location: • Overhead aluminum | | | | | | | | | | |
| Service size: • 200 Amps (240 Volts) | | | | | | | | | | |
| Main disconnect/service box rating: • 200 Amps | | | | | | | | | | |
| Main disconnect/service box type and location: • Corrosion inhibitor Note: present | | | | | | | | | | |
| Main disconnect/service box type and location: • Breakers - basement | | | | | | | | | | |
| Number of circuits installed: • 21 | | | | | | | | | | |
| System grounding material and type: • Bonded within 5' of water system <i>Note:</i> Bonded to an exterior water system but not bonded to the house water system. This should be fixed. | | | | | | | | | | |
| System grounding material and type: • Copper - water pipe and ground rod | | | | | | | | | | |
| Distribution panel rating: • 200 Amps | | | | | | | | | | |
| Distribution panel type and location: • Breakers - basement | | | | | | | | | | |
| Distribution wire material and type: • Copper - non-metallic sheathed • Aluminum - non-metallic sheathed This is feeding to the rear barn | | | | | | | | | | |
| Type and number of outlets (receptacles): • Grounded - typical | | | | | | | | | | |
| Circuit interrupters: Ground Fault (GFCI) & Arc Fault (AFCI): • GFCI - bathroom • GFCI - panel • GFCI - basement • GFCI - kitchen | | | | | | | | | | |
| Limitations | | | | | | | | | | |
| Inspection limited/prevented by: • 50% of the ceiling was covered with plastic or plywood. Inspection limited/prevented by: • Storage Many outlets were not viewable | | | | | | | | | | |
| Recommendations | | | | | | | | | | |
| SERVICE BOX, GROUNDING AND PANEL \ Distribution panel 23. Condition: • Damaged panel or components door is not mounted Task: Provide 24. Condition: • Openings in panel Location: Basement Task: repair | | | | | | | | | | |
| 25. Condition: • <u>Double taps</u> | | | | | | | | | | |

Setting the standard for quality home inspections.


Page 17 of 58

ELECTRICAL

127 Jackson Way, Northampton, MA March 20, 2015

| SUMMARY | ROOFING | EXTERIOR | STRUCTURE | ELECTRICAL | HEATING | INSULATION | PLUMBING | INTERIOR | SITE INFO |
|----------|-----------|----------|-----------|------------|---------|------------|----------|----------|-----------|
| APPENDIX | REFERENCE | | | | | | | | |

Task: Repair



DISTRIBUTION SYSTEM \ Wiring - installation


26. Condition: • <u>Not well secured</u>
service line to outside rear should be fastened better
Location: Basement
Task: Improve
Time: Discretionary

ELECTRICAL



DISTRIBUTION SYSTEM \ Outlets (receptacles)

27. Condition: • <u>No GFI (Ground Fault Interrupter)</u>
Location: Laundry Area
Task: Provide



Report No. 1004, v.3

ELECTRICAL

127 Jackson Way, Northampton, MA March 20, 2015

| SUMMARY | ROOFING | EXTERIOR | STRUCTURE | ELECTRICAL | HEATING | INSULATION | PLUMBING | INTERIOR | SITE INFO |
|----------|-----------------------|------------|-----------|------------|---------|------------|----------|----------|-----------|
| APPENDIX | REFERENCE | | | | | | | | |
| 28. Cond | ition: • <u>GFI t</u> | est faulty | | | | | | | |

Location: Kitchen

Task: Repair

Time: Immediate

HEATING

| 127 Jackson Way, Northampton, MA March 20, 2015 |
|--|
| SUMMARY ROOFING EXTERIOR STRUCTURE ELECTRICAL HEATING INSULATION PLUMBING INTERIOR SITE IN |
| APPENDIX REFERENCE |
| Description |
| General: • Operated Normally During Operation |
| Fuel/energy source: • Propane |
| System type: • Furnace |
| Furnace manufacturer: • Ruud |
| Heat distribution: |
| Ducts and registers |
| insulated galvanized steel and flex duct. The returns are not insulated |
| Exhaust venting method: • Forced draft |
| Approximate age: • <u>3 years</u> |
| Typical life expectancy: • Furnace (conventional or mid-efficiency) 18 to 25 years |
| Main fuel shut off at: • Basement |
| Exhaust pipe (vent connector): • PVC plastic |
| Auxiliary heat: • Wood stove |
| Chimney/vent: • There is a masonry chimney not currently being used. The bricks at and above the roof line are spal and could/should be repaired. |
| Chimney/vent: |
| Metal At the wood stove. |
| At the wood stove. Abandoned |
| At the furnace area. |
| Combustion air source: |
| • Outside |
| The woodstove relies on indoor air. |
| Limitations |
| Inspection prevented/limited by: • Top of chimney too high to see well |
| Fireplace/wood stove: • Stove was in use |
| |
| Recommendations |
| General |
| 29. • Gas fired heating plants should be serviced every other year and upon moving into the new home |
| Task: Service |
| GAS FURNACE \ Ducts, registers and grilles |
| 30. Condition: • Duct extensions not well connected to main trunk. |
| Task: repair |
| |

HEATING

| 127 Jackson Way, Northampton, MA March 20, 2015 | | | | | |
|---|---------|------------|----------|----------|-----------|
| SUMMARY ROOFING EXTERIOR STRUCTURE ELECTRICAL | HEATING | INSULATION | PLUMBING | INTERIOR | SITE INFO |
| APPENDIX REFERENCE | | | | | |
| 31. Condition: • Weak airflow | | | | | |
| Location: Various | | | | | |
| Task: improve | | | | | |
| 32. Condition: • Excessively long runs, excessive elbows | | | | | |
| Location: Various | | | | | |
| Task: improve | | | | | |
| 33. Condition: • Insulation missing, damaged | | | | | |
| At ductwork | | | | | |
| Location: Basement | | | | | |
| Task: improve | | | | | |
| 34. Condition: • Missing | | | | | |
| There is no cold return air ducts on second floor | | | | | |
| Location: Second Floor | | | | | |
| Task: Monitor, improve | | | | | |
| GAS FURNACE \ Mid- and high-efficiency gas furnace | | | | | |
| 35. Condition: • Condensate problems | | | | | |
| condensate pipe goes into ground. | | | | | |
| Location: Basement Task: Monitor | | | | | |
| | | | | | |
| WOOD STOVE \ Cabinet, door and clearances | | | | | |
| 36. Condition: • Floor - combustible clearance inadequate Location: First Floor | | | | | |
| Task: Repair | | | | | |
| Time: Immediate | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |

HEATING

127 Jackson Way, Northampton, MA March 20, 2015

| SUMMARY | ROOFING | EXTERIOR | STRUCTURE | ELECTRICAL | HEATING | INSULATION | PLUMBING | INTERIOR | SITE INFO |
|----------|-----------|----------|-----------|------------|---------|------------|----------|----------|-----------|
| APPENDIX | REFERENCE | | | | | | | | |
| | | | | | | | | | |



6. Floor - combustible clearance inadequate

WOOD STOVE \ Venting

37. Condition: • Rust or obstructed
There is rust where the exhaust pipe meets the stove.
Location: First Floor
Task: Replace
Time: Immediate

CHIMNEY AND VENT \ Masonry chimney

38. Condition: • Loose, missing or deteriorated masonry
In the top 3' of the chimney
Location: Rear
Task: Repair

39. Condition: • <u>Spalling</u> Location: Rear Task: Repair

.... ٨ **FI** / .

| INSULATION AND VENTILATION 127 Jackson Way, Northampton, MA March 20, 2015 | Report No. 1004, v.3 |
|---|--|
| | ATION PLUMBING INTERIOR SITE INFO |
| APPENDIX REFERENCE | |
| Description | |
| Attic/roof insulation material: • Glass fiber • Cellulose | |
| Attic/roof ventilation: • Roof and soffit vents • Gable vent | |
| Mechanical ventilation system for home: • Kitchen exhaust fan • Bathroom | exhaust fan • Laundry room exhaust fan |
| Limitations | |
| Attic inspection performed: • Both attics had storage on 80% of floor. | |
| Recommendations | |
| ATTIC/ROOF \ Insulation | |
| 40. Condition: • <u>Amount less than current standards</u> Task: Further evaluation | |
| | |
| ATTIC/ROOF \ Attic staircase 41. Condition: • <u>Handrails or guardrails missing or unsafe</u> | |
| guard rails could be improved | |
| Implication(s): Trip or fall hazard | |
| Location: First Floor Second Floor Attic Task: Improve | |
| FOUNDATION \ Interior insulation | |
| 42. Condition: • None | |
| Some could be added at the box sill Task: Improve | |
| | |
| 43. Condition: • Exposed combustible insulation windows are covered with styrofoam | |
| Implication(s): Fire hazard | |
| Location: Basement | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |

PLUMBING

127 Jackson Way, Northampton, MA March 20, 2015

| SUMMARY ROOFING EXTERIOR STRUCTURE ELECTRICAL HEATING INSULATION PLUMBING INTERIOR SITE INFO | | | | | |
|--|--|--|--|--|--|
| APPENDIX REFERENCE | | | | | |
| Description | | | | | |
| Water supply source: • Private | | | | | |
| Service piping into building: • Plastic | | | | | |
| Supply piping in building: • Copper • Plastic | | | | | |
| Main water shut off valve at the: • Basement | | | | | |
| Water flow and pressure: • Functional | | | | | |
| Water heater fuel/energy source: • Propane | | | | | |
| Water heater type: • Conventional | | | | | |
| Water heater exhaust venting method: • Direct vent | | | | | |
| Water heater manufacturer: • Ruud | | | | | |
| Tank capacity: • <u>40 gallons</u> | | | | | |
| Water heater approximate age: • TPRV noted • Vacum Relief Valve Noted | | | | | |
| Water heater approximate age: • 3 years | | | | | |
| Typical life expectancy: • 8 to 12 years | | | | | |
| Waste and vent piping in building: • ABS plastic • Cast Iron | | | | | |
| Pumps: • <u>Sump pump</u> | | | | | |
| Gas piping: • Steel • Copper | | | | | |
| Main fuel shut off valve at the: • Basement | | | | | |
| | | | | | |

Limitations

Inspection limited/prevented by: • 20% of the outside walls were not visible due to storage. There is plastic or plywood covering 50% of the ceiling so not visible

Recommendations

WASTE PLUMBING \ Drain piping - performance

44. Condition: • Leak
There is a small leak at the cast iron soil pipe as it exits the home. The foundation hole for the soil pipe should be repaired.
Location: Basement
Task: Improve
Time: Discretionary

PLUMBING 127 Jackson Way, Northampton, MA March 20, 2015

 SUMMARY
 ROOFING
 EXTERIOR
 STRUCTURE
 ELECTRICAL
 HEATING
 INSULATION
 PLUMBING
 INTERIOR
 SITE INFO

 APPENDIX
 REFERENCE
 <t



7. Leak


WASTE PLUMBING \ Venting system

45. Condition: • Missing

The sump pump for the cellar sink is not vented properly. **Implication(s)**: Sewer gases entering the building **Location**: Basement **Task**: Improve **Time**: Immediate

FIXTURES AND FAUCETS \ Toilet

46. Condition: • Loose Location: Second Floor **Task**: Repair



Setting the standard for quality home inspections.

PLUMBING

| SUMMARY | ROOFING | EXTERIOR | STRUCTURE | ELECTRICAL | HEATING | INSULATION | PLUMBING | INTERIOR | SITE INFO |
|----------|-----------|----------|-----------|------------|---------|------------|----------|----------|-----------|
| APPENDIX | REFERENCE | | | | | | | | |

FIXTURES AND FAUCETS \ Bathtub

47. Condition: • Slow drain

Task: Improve

FIXTURES AND FAUCETS \ Shower stall

48. Condition: • The pressure is low and the water hot. The tempering valve needs adjustment.

Location: Second Floor Bathroom

Task: Improve

127 Jackson Way, Northampton, MA March 20, 2015

| SUMMARY ROOFING EXTERIOR STRUCTURE ELECTRICAL HEATING INSULATION PLUMBING IN | |
|--|---------------|
| APPENDIX REFERENCE | |
| Description | |
| | |
| Major floor finishes: • Wood | |
| Major floor finishes: • <u>Concrete</u> | |
| • Vinyl | |
| • Tile | |
| Floor tiles at cellar landing may contain asbestos. | |
| Major wall finishes: • Wood | |
| Major wall finishes: • Plaster/drywall | |
| Major ceiling finishes: • Fiber Board | |
| Major ceiling finishes: • Plaster/drywall • Acoustic tile | |
| Windows: | |
| <u>Single/double hung</u> The tag and a grad in glass | |
| The top sash appear to be fixed in place. • <u>Casement</u> | |
| • <u>Skylight</u> | |
| Glazing: • Single • Double | |
| Exterior doors - type/material: • Wood with glass | |
| Exterior doors - type/material: • <u>Plastic/fiberglass</u> | |
| Evidence of basement leakage: • Sump Pump in Cellar • Sump pump noted | |
| Evidence of basement leakage: • Water • Trough at wall/floor intersection • Dehumidifier in baseme | ont |
| Laundry facilities: | |
| • Washer | |
| • Dryer | |
| Vented to outside | |
| • 120-Volt outlet | |
| Waste standpipe | |
| Gas piping | |
| Kitchen ventilation: • Recirculating type | |
| Bathroom ventilation: • Exhaust fan | |
| Laundry room ventilation: • Clothes dryer vented to exterior | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| Setting the standard for guality home inspections. | Page 28 of 58 |

Setting the standard for quality home inspections.

SUMMARY ROOFING EXTERIOR STRUCTURE ELECTRICAL HEATING INSULATION PLUMBING INTERIOR SITE INFO APPENDIX REFERENCE REFE

Limitations

Inspection limited/prevented by: • Storage/furnishings • Storage in closets/cupboards

Restricted access to:

Basement

80% of basement floor had storage. 50% of basement ceiling covered with plywood or plastic.

Percent of foundation not visible: • 20 %

Recommendations

FLOORS \ General

49. Condition: • <u>Trip hazard</u> Floor transition level is uneven between some rooms **Location**: First Floor Kitchen

Task: Monitor

FLOORS \ Resilient flooring

50. Condition: • Edges are lifting. **Location**: Second Floor Bathroom **Task**: repair

FLOORS \ Subflooring

51. Condition: • <u>Springy</u> Location: First Floor Second Floor Attic

FLOORS \ Concrete floors

52. Condition: • uneven floor trip hazardLocation: BasementTask: Monitor, repairTime: Discretionary

CEILINGS \ General

53. Condition: • Peeling paint should be fixed.Location: VariousTask: ImproveTime: Discretionary

54. Condition: • Typical flaws **Location**: Various **Task**: Monitor

WINDOWS \ Glass (glazing)

55. Condition: • Lost seal on double or triple glazingSkylightLocation: Second Floor Bathroom

| 127 Jackson Way, Northampton, MA March 20, 2015 | | | | - | |
|---|---------|------------|----------|----------|-----------|
| SUMMARY ROOFING EXTERIOR STRUCTURE ELECTRICAL | HEATING | INSULATION | PLUMBING | INTERIOR | SITE INFO |
| APPENDIX REFERENCE | | | | | |
| | | | | | |
| WINDOWS \ Sashes | | | | | |
| 56. Condition: • <u>Stiff</u> | | | | | |
| Some sash are also a little loose | | | | | |
| Implication(s): Reduced operability | | | | | |
| Location: Various | | | | | |
| 57. Condition: • Loose fit | | | | | |
| Implication(s): Chance of damage to finishes and structure | | | | | |
| Location: Throughout | | | | | |
| | | | | | |
| WINDOWS \ Skylight | | | | | |
| 58. Condition: • Leak | | | | | |
| Thee are water stains on the sheetrock. | | | | | |
| Location: Second Floor Bathroom | | | | | |
| Task: Monitor | | | | | |
| | | | | | |
| DOORS \ Doors and frames | | | | | |
| 59. Condition: • Does not latch properly | | | | | |
| door knob at closet needs repair | | | | | |
| Location: Rear Second Floor Bedroom | | | | | |
| Task: Repair | | | | | |
| Time: Discretionary | | | | | |
| CARPENTRY \ Cabinets | | | | | |
| 60. Condition: • Defective hardware | | | | | |
| At sink base | | | | | |
| Location: Kitchen | | | | | |
| Task: Improve | | | | | |
| | | | | | |
| STAIRS \ General | | | | | |
| 61. Condition: • Poor lighting | | | | | |
| Implication(s): Trip or fall hazard | | | | | |
| Location: Various Basement First Floor Second Floor | | | | | |
| Task: Improve | | | | | |
| STAIRS \ Height | | | | | |
| 62. Condition: • Cellar stairway ceiling height is low | | | | | |
| Task: Monitor | | | | | |
| | | | | | |
| STAIRS \ Treads | | | | | |
| 63. Condition: • Worn or damaged | | | | | |
| At cellar and both attics. | | | | | |
| Implication(s): Weakened structure Trip or fall hazard | | | | | |
| Location: First Floor Second Floor | | | | | |
| Task: Improve | | | | | |
| | | | | | |
| | | | | | |

| 127 Jackson Way, Northampton, MA March 20, 2015 | | |
|--|---------------------------------|----------------|
| SUMMARY ROOFING EXTERIOR STRUCTURE ELECTRICAL HEA | ATING INSULATION PLUMBING INTER | RIOR SITE INFO |
| APPENDIX REFERENCE | | |
| STAIRS \ Stringers 64. Condition: • Rot at bottom The bottom stair tread should be replaced. Location: Basement Task: repair | | |
| STAIRS \ Handrails 65. Condition: • <u>Too high</u> It is hard to hold Location: Basement Task: Improve | | |
| STAIRS \ Guardrails 66. Condition: • Should be improved in both attics. Task: Provide | | |
| 67. Condition: • <u>Too low</u> Implication(s): Fall hazard Location: first floor attic Task: improve | | |
| 68. Condition: • <u>Missing</u> Implication(s): Fall hazard Location: second floor attic Task: Provide | | |
| BASEMENT \ Leakage 69. Condition: • Leakage - Read these articles before undertaking Implication(s): Chance of water damage to contents, finishes and/ Location: Basement | . . | |
| BASEMENT \ Wet basement - evidence 70. Condition: • Water on floor Location: Basement Task: monitor | | |
| BASEMENT \ Wet basements - corrective action noted 71. Condition: • Sump pump in basement | | |
| 72. Condition: • Dehumidifier in basement | | |
| 73. Condition: • <u>Peripheral drain</u> Location: Throughout Basement | | |
| EXHAUST FANS \ Exhaust duct 74. Condition: • Weather hood missing or loose Location: Rear Exterior | | |

INTERIOR

| SUMMARY | ROOFING | EXTERIOR | STRUCTURE | ELECTRICAL | HEATING | INSULATION | PLUMBING | INTERIOR | SITE INFO |
|------------------------|--|---------------|--------------|------------|---------|------------|----------|----------|-----------|
| APPENDIX | REFERENCE | | | | | | | | |
| Task: Rep | air | | | | | | | | |
| | t ion: • <u>Not v</u> Second Floo rove | | <u>erior</u> | | | | | | |
| | CES \ Dryer ition: • Plast metal | ic dryer vent | : | | | | | | |
| Location: Task: Rep | First Floor La lace | aundry Area | | | | | | | |
| Time: Imm | nediate | | | | | | | | |

SITE INFO

127 Jackson Way, Northampton, MA March 20, 2015

| SUMMARY R | ROOFING EXTERIOR STRUCTURE ELECTRICAL HEATING | INSULATION PLUMBING INTERIOR SITE INFO | | | | |
|--|--|--|--|--|--|--|
| APPENDIX RE | REFERENCE | | | | | |
| Descriptio | on | | | | | |
| Weather: • C | Cloudy • Ground was frozen • There was snow on the group | und. • There was snow on the roof. | | | | |
| Approximate | te temperature: • 34° | | | | | |
| Attendees: • | Buyer • Buyer's Agent • Seller's Agent | | | | | |
| Access to home provided by: • Seller's agent | | | | | | |
| Occupancy: • The home was furnished during the inspection. | | | | | | |
| Utilities: • All utilities were on during the inspection. | | | | | | |
| Approximate | te inspection Start time: • The inspection started at 9:00 a | a.m. | | | | |
| Approximate | te inspection End time: • The inspection ended at 11:30 a | a.m. | | | | |
| | | | | | | |
| | | | | | | |

END OF REPORT

Setting the standard for quality home inspections.

APPENDIX 127 Jackson Way, Northampton, MA March 20, 2015

| DFING EXTERIOR STRUCTURE ELECTRICAL | HEATING INSULATION PLUM | BING INTERIOR SITE INFO |
|--|--|--|
| RENCE | | |
| 266 CMR: BOARD OF REGISTRA | TION OF HOME INSPECTORS | |
| 266 CMR 6.00: STANDARDS OF PRACTICE 6.01: Access 6.02: Purpose 6.03: General Requirements 6.04: Scope of Home Inspection 6.05: General Limitations and Exclusions of the Home Inspection 6.06: Prohibitions 6.07: Optional Fee Based Services 6.08: Required Distribution of Energy Audit Documents 6.01: Access Che Client shall provide Safe Access and Sufficient Lighting standard are Readily Accessible and Observable. 6.02: Purpose (1) The purpose of a Home Inspection for Residential Buildin with an inspection Report that forthrightly discloses the physic CMR 6.04 which are Readily Accessible and Observable, inc. Hazards as Observed at the time of the inspection | gs, including their attached garages, is to provi cal conditions of the systems and components | ide the Client listed in 266 |
| Hazards as Observed at the time of the inspection.(2) An inspection carried out under the standards of 266 CMF Architectural and/or an Engineering study of the dwelling in or a standard standar | | comprehensive |
| 6.03: General Requirements (1) Inspectors shall: | | |
| Inspectors shall: (a) Use a written contract and provide only the Client with an Client. (b) Observe Readily Accessible and Observable installed syst (c) Submit a confidential written Report only to the Client, with 1. Identify those components specified to be identified in 2 Indicate which systems and components designated for i Indicate which systems and components designated for i Indicate the condition of systems and components so Ins require additional investigation, and areas that have a poter Record the Inspector's name (and the Trainee's name if a Record the Client's name and the address of the property Record the weather conditions at the time of the inspecti Record the existence of obstructions and/or conditions the components. Embed in the Report and/or attach to the Report a copy 6.00: <i>Standards of Practice</i>. Every registered professional Home Inspector, or un such seal and/or bear the name and license number of the F seal on and/or attach his name and license number to a Rep if he/she is the author of such Report or is in charge of its processional Home Inspector or the seal on and/or attach his name and license number to a Rep if he/she is the author of such Report or is in charge of its processional Home Inspector or is in charge of its processional Home Inspector or is in charge of its processional Home Inspector or is in charge of its processional Home Inspector or is in charge of its processional Home Inspector or is in charge of its processional Home Inspector or is in charge of its processional Home Inspector or is in charge of its processional Home Inspector or is in charge of its processional Home Inspector or is in charge of its processional Home Inspector or is in charge of its processional Home Inspector or is in char | ems and components listed in 266 CMR 6.04. hich shall: 66 CMR 6.04. hspection in 266 CMR 6.04 have not been insp pected including those that were found to be in tial for concealed damage. pplicable). inspected. on. at prevented the inspection of the installed sys of itemized questions in 266 CMR 6.03(4)(a) th of 266 CMR 2.00: <i>Definitions</i> and a copy of th e a seal of the design shown below authorized 1 der his supervision, may be stamped with the if tiome Inspector. A registered Home Inspector s ort only if his/her certificate of registration is i | bected. In need of repair, stems and hrough (k). he 266 CMR by the Board. impression of shall impress his |
| 7/24/09 | 266 | 5 CMR – 23 |

| 127 Jackson Way, Northampton, MA March 20, 2015 | |
|--|----------------|
| SUMMARY ROOFING EXTERIOR STRUCTURE ELECTRICAL HEATING INSULATION PLUMBING INTE | RIOR SITE INFO |
| APPENDIX REFERENCE | |
| 266 CMR: BOARD OF REGISTRATION OF HOME INSPECTORS 6.03: continued | |
| John Doe NO 000 PROTECTED TO THE MENTION OF MASO TO THE TEST OF THE TEST OF THE TEST OF THE TEST OF THE THE TEST OF THE TEST. THE TEST OF THE TEST. THE TEST OF THE TEST. THE TEST OF THE TEST. THE TEST OF THE TEST OF THE TEST OF THE TEST. THE TEST OF THE TEST OF THE TEST OF THE TEST. THE TEST OF THE TEST OF THE TEST OF THE TEST. THE TEST OF THE TEST OF THE TEST OF THE TEST. THE TEST OF THE TEST OF THE TEST OF THE TEST. THE TEST OF THE TEST OF THE TEST OF THE TEST. THE TEST OF THE TEST OF THE TEST. THE TEST | |
| (3) The Report shall only inform the Client if additional investigation is required when: | |
| (a) The scope of the repair(s) is unknown, or (b) There is potential for and it is suspected that there is concealed damage, or (c) The subject area is beyond the scope of the Home Inspector's expertise. (4) The Inspector shall notify his/her Client that answers to the following questions should be ascertained from the Seller and/or the Seller's Representative because they are important and relevant to the purchase of the inspected dwelling and may not be Readily Observable through inspection. The Inspector shall have been deemed to satisfy this requirement by embedding and/or attaching the questions listed in 266 CMR 6.03(4)(a) through (k) to the Report. | |
| To the Best of Your Knowledge as the Seller and/or Seller's Representative: | |
| (a) Does the dwelling have a history of seepage, dampness, and/or water penetration into the Basement and/or Under Floor Crawl Space? If so please explain. (b) Has a sump pump ever been installed or used in the Basement/Under Floor Crawl Space? (c) Do you use any type of dehumidification in any part of the dwelling? (d) Are you aware of any mold and/or air quality issues in the dwelling? (e) Is the dwelling on a private sewage system? If the waste system is private, has a Title V inspection been completed, and is the completed Title V Report available for review? Has the dwelling ever been inspected and/or treated for insect infestation? If so, when? What were the chemicals used? (f) Has the dwelling ever been tested for radon gas and/or lead paint? If so when? What were the results? (g) Has the dwelling ever been inspected by an Inspector? | |
| If so, when? Were any problems noted? Is a copy of the inspection Report available? (h) Are the Seller/ Seller's Representative aware of any structural, mechanical, electrical or other material defects that may exist on the property? (i) Has there ever been a fire in the dwelling? If so, when? What chemical cleaners, if any, were used for cleanup? (j) Has there ever been a hazardous waste spill on the property? (k) Is there is an underground storage tank on the property? (5) The Inspector shall not represent to the Seller/Seller's Representative or Client that there is any legal obligation, duty, or requirement on behalf of the Seller/Seller's Representative to answer the questions set forth in 266 CMR 6.03(4)(a) through (k). (6) The Inspector shall not be held liable for the accuracy of third party information. | |
| 1/25/08 266 CMR -24 | |
| Setting the standard for quality home inspections. | Page 35 of 58 |

| 127 Jackson Way, Northampton, MA March 20, 2015 | |
|--|---|
| SUMMARY ROOFING EXTERIOR STRUCTURE ELECTRICAL HEATIN | NG INSULATION PLUMBING INTERIOR SITE INFO |
| APPENDIX REFERENCE | |
| | |
| 266 CMR: BOARD OF REGISTRATION | OF HOME INSPECTORS |
| | |
| 6.03: continued | ald by the Inspector and/or Traince practicing in the |
| (7) Regardless of any additional professional registrations or licenses he Commonwealth of Massachusetts he/she shall conduct his/her Home In: 6.06. However, the standards are not intended to limit Inspectors from: | |
| (a) Reporting observations and conditions in addition to those required i (b) Excluding other systems and components from the inspection if requisition (c) Providing Optional Fee Based Services, as long as they are contracted not prohibited under 266 CMR 6.06. <u>6.04: Scope of the Home Inspection</u> | uested by the Client and noted in the Report. |
| (1) System: Roofing. | |
| (a) The Inspector shall Observe the Readily Accessible and Observable: | : |
| Roof coverings. Exposed roof drainage systems Elachiars | |
| Flashings. Skylights, chimneys, and roof penetrations. Signs of looks on building components. | |
| 5. Signs of leaks on building components.(b) The Inspector shall Identify:1. the type of roof covering materials: Asphalt, Cementious, Slate, Monte Asphalt, Cementious, Slate, Asphalt, Cementious, Slate, Monte Asphalt, | atal and/or Tile Shineles, Duilt un tune (Bald |
| Asphalt, Tar and Gravel, Mineral Covered Rolled Roofing, Ballasted Mechanically Fastened Membrane, Other. | |
| 2. the roof drainage system: Gutters (Aluminum, Copper, Wood, Vin Galvanized, Vinyl, Other) | yl, Other) Leaders/Downspouts (Aluminum, Copper, |
| 3. the chimney materials: Brick, Concrete Block, Metal, Other 4. the methods used to Observe the roofing. | |
| (c) The Inspector shall Report on: 1. Any signs of previous and/or active leaks. | |
| The following exposed Readily Accessible and Observable roofing drainage systems, exposed flashings, skylights, exterior of chimney(s | |
| (d) <u>Exclusions</u> : Including but not limited to 266 CMR 6.04(d)1. and 2., 1. Walk on the roof unless in the opinion of the Home Inspector he/sh | the Inspector shall not be required to: |
| Seller's Representative provides authorization that relieves the Inspec components, and in the opinion of the Inspector, walking on the roof | ctor of all liability of possible damage to the roofing |
| roofing components. 2. Observe and Report On: | I the second s |
| a. Attached accessories including, but not limited to: solar systems, b. The interior of chimney flues. | , antennae, satellite dishes and lightning arrestors. |
| (2) <u>System: Exterior</u> . | |
| (a) The Inspector shall Observe the Readily Accessible and Observable:1. Wall cladding. | |
| 2. Entryway doors and windows. 3. Garage door operators. | |
| 4. Decks, balconies, stoops/landings, steps, areaways/window wells, i 5. Exposed trim (eaves, soffits, fascias, rake, corner, and other trim B | |
| 6. Flashings 7. Driveways, walkways, vegetation, grading, site drainage, and retain | |
| (b) The Inspector shall Identify: 1. Wall-cladding materials: Cementious Siding, Asphalt and/or Wood | - |
| Clapboards, Brick, Other. | i Simigres, i numinum une si viny i Stemig, viose |
| | |
| | |
| | |
| | |
| 1/25/08 | 266 CMR -25 |
| | |
| | |

| 27 Jackson Way, Northampton, MA March 20, 2015 |
|--|
| UMMARY ROOFING EXTERIOR STRUCTURE ELECTRICAL HEATING INSULATION PLUMBING INTERIOR SITE INFO |
| PPENDIX REFERENCE |
| |
| 266 CMR: BOARD OF REGISTRATION OF HOME INSPECTORS |
| 6.04 continued |
| 2. The deck/porch component materials: Brick, Concrete, Concrete Block, Steel, Wood, Other. |
| (c) The Inspector shall Report On the following exposed Readily Accessible and Observable exterior components: Wall cladding. Entryway doors and windows. Deck/porches, balconies, stoops/andings, steps, areaways/window wells, including hand and guard railings. The exposed trim. Flashings. Driveways, walkways, and retaining walls with respect to their effect on the condition of the dwelling and their ability to provide safe egress. Vegetation, grading, site drainage with respect to their effect on the condition of the dwelling. (d) The Inspector shall: Probe exposed Readily Accessible and Observable exterior components where deterioration is suspected: However, probing is NOT required when probing would unduly damage any finished surface. Operate garage doors and representative number of windows and Report their condition and need of repair, if any. Operate garage doors on the greasentative number of windows and Report their condition and need of repair, if any. Operate garage door operator. Report whether or not any garage door operator will automatically reverse or stop when meeting resistance during closing. (e) Exclusions: Including but not limited to 266 CMR 6.04(2)(e)1. through 9., the Inspector shall not be required to Observe and Report the following. Storm doors and windows, screening, shutters, awnings and similar seasonal accessories. Fences, landscaping, trees, swimming pools, patios, sprinkler systems. Safety glaring. Geological conditions (Engineering services). So id conditions (Engineering services). Recreational facilities. Any other dwelling units or addresses in multi-unit buildings. Courbuildings and detached garages. However, should the Inspector of these structures, under 266 |
| CMR 6.07: Optional Fee Based Services, the inspection must comply with the standards of 266 CMR 6.04. 9. Underground utilities, pipes, buried wires, or conduits (Dig Safe) (3) System: Structural Components Exposed in the Basement/Under Floor Crawl Space and Attic Space; Including Signs of Water Penetration. |
| (a) <u>Basement/Under Floor Crawl Space</u>: 1. The Inspector shall Observe the following exposed Readily Accessible and Observable Basement/Under Floor Crawl Space structural components: a. The exposed portions of the foundation. b. The exposed portions of the Basement/Under Floor Crawl Space floor. c. The exposed portions of the superstructure system (girders, sills, floor joists, headers, and sub-floor). d. The exposed portions of the columns and posts. |
| 2. The Inspector shall Identify: a. The type of exposed Basement foundation materials (brick, concrete block, concrete, stone, wood, other). b. The type of exposed Basement floor system (concrete, earth, wood, other). c. The type of exposed Basement superstructure system (girder(s), sills, floor joists, and sub-floor). d. The type of exposed Basement columns and posts (brick, concrete block, concrete, steel, wood, other). |
| 1/25/09 266 CMR -26 |

| 127 Jacks | on Way, Nor | nampton, MA March 20, 2015 | |
|-----------|-------------|--|-----------------------|
| SUMMARY | ROOFING | EXTERIOR STRUCTURE ELECTRICAL HEATING INSULATION PLUMBI | NG INTERIOR SITE INFO |
| APPENDIX | REFERENCE | | |
| | | | |
| | | 266 CMR: BOARD OF REGISTRATION OF HOME INSPECTORS | |
| | 6.04. | | |
| | | ontinued The Inspector shall Report On the following exposed Readily Accessible and Observable structural comp | onents |
| | - | a. The foundation. b. The floor system. | Siend. |
| | | c. The superstructure system. d. The columns and posts | |
| | 2 | The Inspector shall: a. Probe exposed Readily Accessible and Observable structural components where deterioration is suspec probing is NOT required when probing would unduly damage any finished surface. | ted; however, |
| | | b. Note the methods used to Observe Under Floor Crawl Spaces. c. Note obstructions, unsafe access, and dangerous or adverse situations that prevented him/her from inspiritors noted in 266 CMP 6.0(12)(2)(2) at the used here. | ecting the |
| | | items noted in 266 CMR 6.04(3)(a)3.a. through d d. Note signs of previous and/or active water penetration into the Basement, Under Floor Crawl Space and including the presence of sump pumps and dehumidifiers. | 1 attic |
| | 5 | Exclusions: Including but not limited to 266 CMR 6.04(3)(a)5.a. through d., the Inspector shall not be req a. Collect engineering data such as the size, span, spacing, species, section modulus, slenderness ratio and of elasticity of the structural members. | |
| | | b. Provide access to the items being inspected (Responsibility of Client/Seller/Seller's Representative). c. Enter the Under Floor Crawl Space If it is not Readily Accessible, | |
| | | ii. If a coess is obstructed and/or if entry could damage the property iii. If a Dangerous or Adverse Situation is suspected and Reported by the Inspector. | |
| | | d. Observe and Report On Wood destroying insects, rodents and/or vermin unless specifically contracted (Independent Pest Control/Extermination Service). | for in writing. |
| | (b <u>)</u> | Attic Space. | |
| | | The Inspector shall Observe the following exposed Readily Accessible and Observable roof framing struct omponents: The exposed portions of the roof framing, including the roof sheathing. The Inspector shall Identify: | tural |
| | | a. The type of framing: Rafters, Collar Ties, Tie Beams, Trusses, Other b. Roof Sheathing: Boards, Oriented Strand Board, Plywood, Other. | |
| | 2 | c. The methods used to Observe attics (through a hatch or while standing in the attic space). The Inspector shall Report On: | |
| | | a. The presence and/or lack of flooring, obstructions, unsafe access, and dangerous or adverse situations the him/her from inspecting the items noted in 266 CMR 6.04(3)(b)2. b. The following exposed Readily Accessible and Observable structural components of the roof framing: | hat prevented |
| | | i. The roof framing (Rafters, Collar Ties, Tie Beams, Rafter Ties, Trusses, Beams, Other) ii. Sheathing Materials (Boards, Oriented Strand Board, Plywood, Other). | |
| | 2 | c. The presence of a light. The Inspector shall: | |
| | | a. Probe exposed Readily Accessible and Observable structural components where deterioration is suspec probing is NOT required when probing would unduly damage any finished surface. b. Note the presence of a light. | ted: However, |
| | - | Exclusions: Including but not limited to 266 CMR 6.04(3)(b)5.a. through e. the Inspector shall not be required. | aired to: |
| | | a. Enter the Attic Space: i. If it is not Readily Accessible, | |
| | | | |
| | | | |
| | | | |
| | | | |
| | 1/25/08 | 266 C | CMR -26.1 |
| | | | |
| | | | |
| | | | |

| MMARY ROOFING E | EXTERIOR STRUCTURE ELECTRICAL | HEATING INSULATION PLUMBING INTERIOR | SITE INF |
|-------------------------|--|---|----------|
| | | | |
| PENDIX REFERENCE | | | |
| | | | |
| | 266 CMR: BOARD OF REGISTRA | ATION OF HOME INSPECTORS | |
| 6.04: cor | ntinued | | |
| | | the property | |
| | If access is obstructed and/or if entry could damage If a Dangerous or Adverse Situation is suspected at Walk on the exposed and/or insulation covered framin | nd Reported by the Inspector. | |
| с. | Collect engineering data such as the size, span, spacing | g, species, section modulus, slenderness ratio and/or modulus | |
| d. | elasticity of the structural members. (Engineering serv Provide access to the items being inspected. | | |
| | Observe and Report On Wood destroying insects, rode adependent Pest Control/Extermination Service). | ents and/or vermin unless specifically contracted for in writing. | |
| (4) <u>Sys</u> | tem: Electrical. | | |
| (a) The | Inspector shall Observe the Readily Accessible and O | bservable Electrical Systems and Components: | |
| 1. Th | e exterior of the exposed service entrance conductors. acterior receptacles. | | |
| 3. Th | e service equipment, grounding system, main overcur | rent device, and the interior of the service and distribution | |
| 4. Th | | nductors, their overcurrent devices, and the compatibility of | |
| 5. Ra | ampacities and voltages. Indom interior receptacles. | | |
| | e number of branch circuits and overcurrent devices in | the panel enclosures. | |
| | Inspector shall Identify: a service as being overhead or underground, cable, en | cased in conduit, other. | |
| 2. The other | | materials (copper, copper-cladded aluminum, aluminum, | |
| | the type of Interior Wiring (Armored Cable, Conduit, The mblies, Other). | ıbing, Nonmetallic Cable, Knob and Tube, Flat Cable | |
| 4. Th | e location of the service and distribution panels and in | dicate whether they are Readily Accessible and Observable. nect (30, 60, 100, 125, 150 and/or 200 amp, other service, 120, | |
| 120/2 | 240, 120/208-volt system). by of the overcurrent devices that are in the off position | • | |
| | | ". ssible and Observable Electrical Systems and Components: | |
| 1. Th | e electrical service equipment including the service an | d distribution panels. | |
| any) | - | nd polarity, grounding and ground fault protection issues (if | |
| 4. Th | ny polarity or grounding issues of the receptacles requi the exposed and Readily Accessible and Observable into | erior wiring. | |
| 5. Co | onditions that prevented him/her from inspecting any o | f the items noted above. | |
| (d) The 1. <u>Te</u> | Inspector shall: est: | | |
| a. | The polarity and grounding of a representative sample | of the Readily Accessible two and three-prong receptacles | |
| th | roughout the dwelling. The polarity and grounding of all un-dedicated bathroo | | |
| с. | The polarity and grounding of all Readily Accessible, | non-dedicated receptacles in the attached garage and on the ents, and check to see if they are ground fault protected. | |
| d. | The operation of all Readily Accessible Ground-fault The operation of all Readily Accessible Arc Fault Cur | Circuit Interrupters. | |
| | All bathroom and kitchen countertop receptacles to see | • | |
| 2. <u>No</u> | ote: | | |
| | The reason(s) for not removing any panel covers. | | |
| b. | The location of the service and distribution panels. | | |
| | | | |
| 1/ | 25/08 | 266 CMR - 26.2 | |
| | | | |
| | | | |

| 127 Jacks | on Way, Nor | thampton, M | A March 20 |), 2015 | | | | | |
|-----------|-------------|--|---|---|---|---|---|------------------|-----------|
| SUMMARY | ROOFING | EXTERIOR | STRUCTURE | ELECTRICAL | HEATING | INSULATION | PLUMBING | INTERIOR | SITE INFO |
| APPENDIX | REFERENCE | | | | | | | | |
| | | | | | | | | | |
| | | 266 CN | MR: BOARD | OF REGISTRA | ATION OF I | HOME INSPEC | TORS | | |
| | 6.04: | continued | | 51 10000110 | | | 10115 | | |
| | 010 11 | | of aluminum wiring, | and | | | | | |
| | | termination con | mpound, and | essible and Observab | | onductor terminations | s are coated with a | | |
| | | d. If the electrical e. If the water pip f. If the neutral ar g. The compatibil h. The functional i. The existence o | l system is attached bing is not bonded to nd equipment-groun lity of the overcurre ity of ground-fault a | to both the city and o the electrical syste ad terminal bars are lent devices and the si and arc fault protecte ection devises on all | dwelling side of em within the first bonded to the pa ize of the protect ed receptacles, it | of the water piping and rst five feet of its entry | ry into the Basement. -fusing). by the required testin | ng. | |
| | | (e) Exclusions: Incl | uding but not limite | d to 266 CMR 6.04(| (4)(e)1. through | 6., the Inspector shal | ll not be required to: | | |
| | | circuit interrupting of 2. Determine the ad on the sufficiency of 3. Insert any tool, pr 4. Test or Operate a 5. Dismantle any ele However, the Inspec | current capacity. (E lequacy of the groun of the electric distrib robe, or testing devi my overcurrent devi ectrical device or co- ctor is not required 1 ible, if there are Dar /or covering materia | ngineering services) and/or the in place ution system in the l ice inside the panels. ice except Ground-fa ontrol other than to re to remove the cover- ngerous or Adverse s |). e systems to pro Dwelling (Engir ault Circuit Inter remove the cover s of the service a | with the panel and/or ovide sufficient power neering/Electrical Ser rrupters and Arc Faul ers of the service and of and distribution panel ent, or when removal w | er to the dwelling, or r rvices). It Interrupters. distribution panels. els if the panel covers | reflect s are | |
| | | b. Test for Electro c. Low voltage sy d. Smoke and car e. Telephone, sec distribution system | o-Magnetic fields. (ystems, doorbells, the bon monoxide detect urity alarms, cable 7 m. | ctors (Seller's respor | nsibility, M.G.L. ther ancillary wi | c. 148, § 26E and 52 iring that is not a part | | rical | |
| | (5) |) System: Plumbing. | | | | | | | |
| | | | dily Accessible and ls, including suppor nucets. w. | | • water supply ar | nd distribution systen | n including: | | |
| | | | aste, and vent pipin | Observable exterior g; piping supports a | | ain waste and vent sy ion. | /stem, including: | | |
| | | | | | | | | | |
| | 1/25/08 | | | | | | 266 CMR -26 | j.3 | |
| | | | | | | | | | |

| 127 Jackson Way, No | | ch 20, 2015 | | | | |
|---------------------|--|-------------------------------|------------------------|------------------------------|----------------|-----------|
| SUMMARY ROOFING | EXTERIOR STRUCT | JRE ELECTRICAL | HEATING | INSULATION PLUN | IBING INTERIOR | SITE INFO |
| APPENDIX REFERENCE | | | | | | |
| | | | | | | |
| | 266 CMR: BOA | ARD OF REGISTRA | ATION OF HO | ME INSPECTORS | | |
| 6.04: | continued | | | | | |
| | Hot water systems including: a. Water heating equipment. | | | | | |
| | b. Normal Operating Controls c. The presence of Automatic | | | | | |
| | d. The exterior of the chimner | ys, thimbles and vents. | | | | |
| | (b) The Inspector shall Identify: 1. The type(s) and condition of a 2. The type(s) and condition of a Plastic, Steel, Other). | | | • | | |
| | The type of water heating equ water heating equipment (gallor The location of the main shut | is and/or gallons per minut | | her), and the nameplate ca | pacity of the | |
| | (c) The Inspector shall Report On | | | | | |
| | The water heater. The exposed flue piping and the second sec | | | e. | | |
| | (d) The Inspector shall: | Jusei vable waste and wate | r distribution system | | | |
| | 1. Operate all plumbing fixtures 2. Note: | where practical, including | their faucets if read | ily Accessible. | | |
| | a. The presence of a pressure/ b. The existence of Cross Cor | nnections if Readily Acces | | | | |
| | c. The existence of any visible d. conditions that prevented h | | y of the Plumbing C | omponents and Systems | | |
| | (e) <u>Exclusions</u>: Including but not 1 1. Test the operation of any valve 2. Collect engineering data on the | e except Readily Accessib | le water closet flush | valves and fixture faucets | - š. | |
| | (Engineering/Plumbing services 3. Report On the adequacy and/ | or the efficiency of the in p | | vide sufficient hot water to | the dwelling, | |
| | sufficient water supply, or drain 4. State the effectiveness of anti 5. Determine whether water sup | -siphon devices (Engineeri | ing/Plumbing servic | | recontativa | |
| | responsibility).Observe, Operate, or Report (| | terns are public of p. | iivate (Senei/Senei S Keph | esentative | |
| | a. The exterior hose bibs. b. Water conditioning system | | | | | |
| | c. Fire and lawn sprinkler sys d. On-site or public water sup | ply quantity and quality. | | | | |
| | e. On-site (Title V Inspection f. Foundation sub drainage sy | stems. | | tems. | | |
| | g. whirlpool tubs, except as to h. interior of flue linings. i. Underground utilities, pipes | | - | | | |
| | j. Equipment related to on-site k. Water filtration Componen | e water supply systems. | | | | |
| (6) <u>S</u> | ystem: Heating. | | | | | |
| | (a) The Inspector shall Observe the Components and Systems:1. Heating equipment including. | | - | - | vable heating | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| 1/25 | 5/08 | | | 266 CMR -2 | 26.4 | |
| | | | | | | |
| | | | | | | |

| 127 Jackson Way, Northampton, MA March 20, 2015 | |
|---|--|
| SUMMARY ROOFING EXTERIOR STRUCTURE ELECTRICAL | HEATING INSULATION PLUMBING INTERIOR SITE INFO |
| APPENDIX REFERENCE | |
| 266 CMR: BOARD OF REGISTRA | ATION OF HOME INSPECTORS |
| 2. Normal operating controls 3. Automatic Safety Controls. 4. The exterior of the chimneys, thimbles and vents. 5. Solid fuel heating devices. 6. Heating distribution systems including Readily Accessiti insulation, air filters, registers, radiators, fan coil units, cor 7. Insulation. 8. The presence of an installed heat source in each habitable 9. The exposed flue piping and the existence of a thimble(10) The presence of a fireplace(s) and the operation of their (b) The Inspector shall Identify: The type of energy source (Coal, Electric, Gas, Heat Pun 2. The heating equipment (Electric, Hot Air, Hot Water, St 3. The type of distribution system: | nvectors. le room including kitchens and bathrooms. s). r damper(s). mp, Oil, Wood, Other). |
| a. Piping: (Black Iron, Copper, Other). b. Duct work: (Aluminum, Fiberglass, Steel, Other). (c) The Inspector shall Report On the following permanently system components: The heating equipment. The distribution system. The flue piping and the existence of a thimble(s). The fireplace hearth(s) The fireplace damper(s). | installed and Readily Accessible and Observable heating |
| and associated piping must be removed per 527 CMR. 2. If possible, have the Seller and/or the Seller's Represent not possible for Seller or Seller's Representative to Operating Operating Controls and Report On condition of the heating | being utilized by other appliances. posed abandoned oil lines, meters, <i>etc.</i>) Abandoned oil tanks ative Operate the systems using Normal Operating Controls. If e system, the Inspector shall Operate system using Normal |
| (e) <u>Exclusions</u>: Including but not limited to 266 CMR 6.04(7 1. Test and/or inspect the heat exchanger. This requires dis (Engineering services/Heating services). 2. Collect engineering data on the size of the heating equip (Engineering/Heating services). 3. Report On the adequacy or uniformity of the in place sy dwelling (Engineering/Heating services). 4. Operate heating systems when weather conditions or oth electrical and/or fuel supply to the unit is in the off position 5. Ignite or extinguish solid fuel and/or gas fires. 6. Identify the type of insulation coverings. 7. Observe, Identify, or Report On: | smantling of the furnace cover and possible removal of controls. oment and/or the size or length of the distribution systems. (stem(s) to heat the dwelling and/or the various rooms within the her circumstances may cause equipment damage, or when the |
| 1/25/08 | 266 CMR – 26.5 |

| SUMMARY RO | DOFING EXTERIOR STRUCTURE ELECTRICAL HEATING INSULATION PLUMBING INTERIOR SITE INFO |
|--------------|--|
| APPENDIX REF | ERENCE |
| | |
| | |
| | 266 CMR: BOARD OF REGISTRATION OF HOME INSPECTORS |
| | 6.04: continued |
| | b. Fireplace inserts flue connections. c. Humidifiers. |
| | d. Electronic air filters. e. Active underground pipes, tanks, and/or ducts. However, the Inspector must Report their existence if it is known. |
| | f. Active oil tanks. g. The uniformity or adequacies of heat supply to the various rooms. |
| | (7) System: Central Air Conditioning. |
| | (a) The Inspector shall Observe: |
| | The following exposed Readily Accessible and Observable central air conditioning components: a. Cooling and air handling equipment. |
| | b. Normal operating controls.2. The following exposed Readily Accessible and Observable distribution systems: Fans, pumps, ducts and piping, with |
| | supports, dampers, insulation, registers, fan-coil units, condensers, the presence of insulation on the distribution system. (b) The Inspector shall Identify the type of distribution system (Duct work: Aluminum, Fiberglass, Steel, Other). |
| | (c) The Inspector shall Report On the following exposed Readily Accessible and Observable central air conditioning components: |
| | The distribution system The insulation on the exposed supply ductwork. |
| | 3. The condition of the condenser and air-handling unit. (d) The Inspector shall: |
| | If possible, have the Seller and/or the Seller's Representative Operate the systems using Normal Operating Controls Open Readily Accessible Operable Access Panels provided by the manufacturer or installer for routine homeowner meintenance and React On conditions Observed |
| | maintenance and Report On conditions Observed. 3. Note a. Whether or not the cold gas line is insulated. |
| | a. Whether there is, a service receptacle and a visible service disconnect switch in the area of the condenser and air handling equipment. |
| | (e) <u>Exclusions</u> : Including but not limited to 266 CMR 6.04(7)(e)1. through 7., the Inspector shall not be required to: 1. Collect engineering data on the size of the cooling equipment, the size or length of the distribution systems. |
| | Identify the type of insulation coverings. Observe, Identify, or Report On air filters and/or their effectiveness. |
| | 4. Have the Seller and/or the Seller's Representative Operate the cooling systems when weather conditions or other circumstances may cause equipment damage, or when the electrical supply to the unit is in the off position. |
| | 5. Observe, Identify, or Report On evaporator coils (Requires dismantling of the plenum cover and possible removal of controls which is HVAC technician work). |
| | Observe, Identify, or Report On non-central air conditioners. Report On the adequacy or uniformity of the in place system(s) to cool the dwelling and/or the various rooms within |
| | the dwelling (Engineering/Heating services). |
| | (8) <u>System: General Interior Conditions</u> . |
| | (a) The Inspector shall Observe: 1. Walls, ceiling, and floors. |
| | Steps, stairways, balconies, hand and guard railings. Counter tops and a representative number of cabinets. |
| | A representative number of doors and windows. Separation walls, ceilings, and doors between a dwelling unit and an attached garage or another dwelling unit. |
| | (b) The Inspector shall Identify: |
| | 1. The type of exposed floor material (brick, carpet, ceramic tile, linoleum, slate, vinyl tile, wood, other). |
| | |
| | |
| | 1/25/08 266 CMR -26.6 |
| | 1/20/06 200 CMR-20.0 |
| | |
| | |

| 127 Jackson Way, Northampton, MA March 20, 2015 | |
|--|--|
| SUMMARY ROOFING EXTERIOR STRUCTURE ELECTRICAL HEAT | TING INSULATION PLUMBING INTERIOR SITE INFO |
| APPENDIX REFERENCE | ROOFING EXTERIOR STRUCTURE ELECTRICAL HEATING INSULATION PLUMBING INTERIOR SITE INFO |
| | |
| 266 CMP+ BOARD OF REGISTRATION | OF HOME INSPECTORS |
| | OF HOME INSPECTORS |
| 6.04: continued | |
| | s, laminates, paneled, plaster, gypsum wallboard, |
| (c) The Inspector shall Report On: | dlboard, plaster, wood, other). |
| | |
| 4. The condition of the interior stairs, hand and guard railings. | |
| 6. The interior doors Observed and tested. | |
| (d) The Inspector shall operate a representative number of doors, wind | |
| 1. Observe and Report On the following: | |
| b. Draperies, blinds, or other window treatments. | lls, ceilings, and floors. |
| 2. Determine the fire safety rating of any walls, ceilings, and doors | between a dwelling unit and an attached garage or |
| | |
| | |
| 1. Exposed insulation in unfinished spaces. | Observable Components and Systems: |
| 3. Bathroom venting systems | |
| 1. The type of ventilation in the attic space (None, Ridge, Soffit, An | ea, Power Vent, Gable, Eave, Mushroom, Turbine, |
| 2. The existence and/or absence of bathroom ventilation other than | |
| 1. Exposed insulation in unfinished spaces. | d Observable Components and Systems: |
| 3. Bathroom venting systems. | |
| 1. The absence of insulation in unfinished space at Conditioned Sur | faces. |
| (e) Exclusions: Including but not limited to 266 CMR 6.04(9)(e)1. thr | ough 5., the Inspector shall not be required to Observe |
| 1. The type(s) and/or amounts of insulation and/or its material make | э-ир. |
| 3. Venting equipment that is integral with household appliances. | |
| 5. The adequacy, uniformity and capacity of the in place system(s) | to ventilate the various areas of the dwelling |
| 6.05: General Limitations and Exclusions of the Home Inspection | |
| | arth in 266 CMP 6.04 are visual and not Tachnically |
| Exhaustive. | |
| • • • | e appreade to residential buildings with four of less |
| | |
| | |
| | |
| 1/25/08 | 266 CMR – 26.7 |
| | |
| | |
| | |

| 127 Jackson Way, Northampton, MA March 20, 2015 | |
|---|--|
| SUMMARY ROOFING EXTERIOR STRUCTURE ELECTRICAL HEATING | INSULATION PLUMBING INTERIOR SITE INFO |
| APPENDIX REFERENCE | |
| | |
| | |
| 266 CMR: BOARD OF REGISTRATION OF H | IOME INSPECTORS |
| 6.05: continued | |
| (2) <u>General Exclusions</u> . | |
| (a) Inspectors shall not be required to Report On:1. The remaining life expectancy of any component or system.2. The causes of the need for repair.3. The materials for corrections of the problem. | |
| 4. The methods of repair other than to indicated the repair should comply we codes and sound construction practices. | |
| Compliance or non-compliance with applicable regulatory requirements t Any component or system not covered by 266 CMR 6.04. Cosmetic items. | |
| 8. Items that are not Readily Accessible and Observable, underground items 9. Systems or Components specifically excluded by Client (noted in writing | |
| (b) Inspectors shall not be required to perform or provide any of the following CMR 6.04: | under the Home Inspection specified in 266 |
| Offer warranties, guarantees and/or insurance policies of any kind on the Collect any engineering data (the size of structural members and/or the or equipment). Inspect spaces that are not Readily Accessible and Observable. Enter any | utput of mechanical and/or electrical |
| damage the property or its components, or be dangerous and unsafe to the In and Reported by the Inspector.4. Disturb or move insulation, stored and/or personal items, furniture, equip | nspector or other persons, as determined by |
| obstructs access or visibility. 5. Determine the effectiveness of any system installed to control or remove 6. Predict future conditions, including but not limited to failure of Compone 7. Project operating costs of Components. | |
| B. Determine extent or magnitude of damage or failures noted. Operate any System or Component which does not respond to normal operation. | erating controls. |
| Test for radon gas. Determine the presence or absence of pests including but not limited to: Determine the energy efficiency of the dwelling as a whole or any indiv | rodents or wood destroying insects. |
| dwelling. 13. Perform Environmental Services including determining the presence or | verifying the absence of any micro organisms |
| or suspected hazardous substances including, but not limited to, carbon mor Volatile Organic Compounds, PCB's, asbestos, UFFI, toxins, allergens, mol electromagnetic radiation, noise, odors, or any contaminants in soil, water, a | ds, carcinogens, lead paint, radon gas, |
| hazard not listed in 266 CMR 6.05(2)(a) and (b). 14. Evaluate acoustical characteristics of any system or component. 15. Inspect surface and subsurface soil conditions. | |
| 6.06: Prohibitions | |
| Inspectors are prohibited from: | |
| (1) Reporting on the market value of property or its marketability and/or the(2) Advising their Client about the advisability or inadvisability of the purch | |
| | |
| | |
| | |
| 1/25/08 | 266 CMR – 26.8 |
| | |

| 127 Jacks | Way, Northampton, MA March 20, 2015 | |
|-----------|--|----------------|
| SUMMARY | ROOFING EXTERIOR STRUCTURE ELECTRICAL HEATING INSULATION PLUMBING INTER | RIOR SITE INFO |
| APPENDIX | EFERENCE | |
| | | |
| | 266 CMR: BOARD OF REGISTRATION OF HOME INSPECTORS | |
| | | |
| | 6.06: continued(3) Testing Automatic Safety Controls. | |
| | (4) Activating the sump pumps and/or dehumidifiers. | |
| | (5) Offering or performing any act or service contrary to law and/or 266 CMR 6.00. | |
| | (6) Determining the cost of repairs of any item noted in their Report and/or inspected by them and/or their firm. | |
| | (7) Offering to make and/or perform any repair, provide any remedy: including but not limited to performing engineering, architectural, surveying, plumbing, electrical and heating services, pest control (treatment), urea formaldehyde or any other job function requiring an occupational license and/or registration (in the jurisdiction where the inspection had taken place) on a Dwelling, and/or Residential Building inspected by his/her firm. The only exception is if those repairs and/or services are part of a negotiated settlement of a complaint and/or claim against the Inspector and/or the firm he/she/represents. | |
| | (8) However, nothing in 266 CMR 6.06 shall prohibit the Inspector and/or his/her/firm from offering consulting services on a Dwelling, and/or Residential Building his/her firm has not inspected as long as the consulting service is not pursuant to the sale and/or transfer of the property and/or dwelling. | |
| | (9) Operating any system or component that is shut down or otherwise inoperable. (However, the Inspector shall recommend the Seller and/or the Seller's Representative demonstrate that those systems and/or components are functional). | |
| | (10) Turn on any electrical or fuel supply and/or devices that are shut down. (However, the Inspector shall recommend the Seller and/or the Seller's Representative demonstrate that those systems and/or components are functional). | |
| | 6.07: Optional Fee Based Services | |
| | There are certain risks inherent in the purchase of property and a Home Inspection is inherently limited in its scope and depth. The information gained from Home Inspection conforming to 266 CMR 6.04 may reduce some of those risks, but the Home Inspection is not intended to provide the Client with protection from all of the risks involved. | |
| | The Home Inspector may provide Optional Fee Based Services addressing items including, but not limited to, those excluded in 266 CMR 6.04 provided the service is specifically contracted for in writing and/or included in the Report, and do not include the physical repair, abatement, or treatment to the Dwelling, and/or Residential Building being inspected, and is not prohibited under 266 CMR 6.06. | |
| | To offer any such services that require an occupational license and/or registration, the Inspector shall hold a valid registration and/or occupational license in the jurisdiction where the inspection is taking place. The Inspector shall inform the Client in writing that he/she is so registered/licensed and is therefore qualified to go beyond the standards of 266 CMR 6.04. | |
| | 6.08: Required Distribution of Energy Audit Documents | |
| | (1) <u>Purpose and Scope</u> . The purpose of 266 CMR 6.08 is to promote the informed use of energy audits by providing a document, outlining the procedures and benefits of a home energy audit, to buyers of residential dwellings at or before the time of closing. | |
| | (2) <u>Requirement</u> . Home Inspectors shall provide a document outlining the procedures and benefits of a home energy audit to all Clients purchasing a single-family residential dwelling, a multiple-family residential dwelling with less than five dwelling units, or a condominium unit in a structure with less than five dwelling units. | |
| | (3) <u>Distribution of Document -Availability, Timing, and Format</u> . The Board shall make a copy of the document to be distributed available on its website. The document must be provided to the buyer of the real estate at or before closing. | |
| | 7/24/09 266 CMR -26.9 | |
| | | |

| UMMARY | ROOFING EXTERIOR STRUCTURE ELECTRICAL HEATING INSULATION PLUMBING INTERIOR SITE IN |
|---------|--|
| PPENDIX | REFERENCE |
| | |
| | |
| | 266 CMR: BOARD OF REGISTRATION OF HOME INSPECTORS |
| | 6.08: continued |
| | |
| | (4) Prohibition of Additional Fees. No additional fees shall be imposed upon or collected from the buyer or seller of the real estate in connection with the provision of such document. |
| | REGULATORY AUTHORITY |
| | 266 CMR 6.00: M.G.L. c.13, § 96 and c. 112, §§ 221 through 226. |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |

7/24/09

266 CMR - 26.10

APPENDIX 127 Jackson Way, Northampton, MA

| 127 Jacks | on Way, North | mpton, MA March 20, 2015 | |
|-----------|---------------|---|-----------|
| SUMMARY | ROOFING | EXTERIOR STRUCTURE ELECTRICAL HEATING INSULATION PLUMBING INTERIOR | SITE INFO |
| APPENDIX | REFERENCE | | |
| | | | |
| | | | |
| | | | |
| | | 266 CMR: BOARD OF REGISTRATION OF HOME INSPECTORS | |
| | | 266 CMR 2.00: DEFINITIONS | |
| | | | |
| | | | |
| | | 2.01: Definitions | |
| | | 2.01: Definitions | |
| | | As used in 266 CMR 2.00 through 11.00, the following definitions shall apply: | |
| | | Agent. Seller's/owner(s) representative and/or person authorized to act on behalf of the seller/ owner(s) including a real estate broker or salesperson as defined in M.G.L. c 112, § 87PP. | |
| | | Associate Home Inspector. A person licensed pursuant to M.G.L. c. 112, § 223, conducting a | |
| | | Home Inspection of residential building(s) under the supervision of a licensed Home Inspector. | |
| | | Attic Space. The unfinished space between the ceiling joists of the top story and the roof rafters. | |
| | · · · | Automatic Safety Controls. Devices designed and installed to protect systems and components from unsafe conditions. | |
| | | Architectural Services. As defined in M.G.L. c. 112, §§ 60A through 60O (architect's license required). | |
| | | <u>Architectural Study</u> . A study requiring Architectural Services. | |
| | | Basement/Cellar. That portion of a Dwelling that is partly or completely below grade. | |
| | | <u>Board</u> . The Board of Registration of Home Inspectors established pursuant to M.G.L. c. 13, \S 96. | |
| | | <u>Branch Circuit</u> . The circuit conductors between the final overcurrent device protecting the circuit and the outlet(s). | |
| | · · | Buyer's Broker. A real estate broker or salesperson, as defined in M.G.L. c 112, § 87 YY14, who has a written contractual agreement or a written agency disclosure between the buyer and the real estate broker specifying that the real estate broker is acting exclusively for the buyer as a buyer's broker. | |
| | | Central Air Conditioning. A system that uses ducts to distribute cooled and/or dchumidified air to more than one room or uses pipes to distribute chilled water to heat exchangers in more than one room, and which is not plugged into an electrical convenience outlet. | |
| | | <u>Client</u> . A person who engages the services of a Home Inspector for the purpose of obtaining inspection of and a written Report On the condition of a Dwelling and/or Residential Building(s). | |
| | | <u>Component</u> . A Readily Accessible and Observable element comprising a part of a system and which is necessary for the safe and proper function of the system. | |
| | | <u>Conditioned Surface</u> . The surface of the floor and/or ceiling that is being mechanically cooled and/or heated. | |
| | | <u>Continuing Education Credits</u> . Formal coursework covering the elements directly related to the inspection of homes and/or commercial buildings. One contact hour shall equal one credit, | |
| | | <u>Continuing Education Program</u> . Formal presentation such as a lecture or interactive session with specified learning objectives at which Registrants can earn Continuing Education Credits approved by the Board based on criteria set forth in 266 CMR 5.00 <i>et seq.</i> | |
| | | <u>Contract</u> . The written agreement between the Client and the Home Inspector, which spells out the responsibilities and duties of each party and the fee to be paid for the inspection. | |
| | • | 1/25/08 266 0 km 5 | |
| | | 12300 266 CMR - 5 | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |

| MMARY ROOFING EXTERIOR | STRUCTURE ELECTRICAL HEATING INSULATION PLUMBING INTERIOR SITE IN |
|------------------------|---|
| PENDIX REFERENCE | |
| | |
| | |
| | |
| | 266 CMR: BOARD OF REGISTRATION OF HOME INSPECTORS |
| 2.01 | continued |
| 2.01. | Cross Connection. Any physical connection or arrangement between potable water and any |
| , , | source of contamination. |
| | Dangerous or Adverse Situations. Situations that pose a threat of injury to the Inspector's health and welfare as determined by the Inspector. |
| | Direct Supervision. Direct supervision means on-site and in-view observation and guidance of |
| | a supervisee who is performing an assigned activity during a Home Inspection. |
| | <u>Dismantle</u> . To take apart or remove any component, device, or piece of equipment that is bolted, screwed, or fastened that a homeowner in the course of normal household maintenance would not dismantle other than the electrical panel cover(s). |
| | Division. The Division of Professional Licensure. |
| | Dwelling. A house, townhouse, condominium, cottage, or a Residential Building containing not |
| | more that four dwelling units under one roof. |
| | Educational Training Credits. Formal coursework covering the elements of the fundamentals of Home Inspection. One contact hour shall equal one credit. |
| | Provider. A person approved by the Board to offer continuing education credits. |
| | <u>Electrical Services</u> . As defined in M.G.L. c. 141, M.G.L. c. 148, §§ 10D and 10E, and 527 CMR 12.00 (electrician license required). |
| | Engineering Services. As defined in M.G.L. c. 112, §§ 81D through 81T. (Engineering license |
| | required). |
| | Engineering Study. A study requiring Engineering Services. Environmental Services. Services that require physical samples to be taken and analyzed by a |
| | aboratory to determine the type of and presence of contaminates and/or organic compounds and as defined in M.G.L. c. 112, §§ 81D through 81T and § 87LL. (License required). |
| | Exclusions. Those items that are not part of and/or included in the 266 CMR 6 00: Standards |
| | of Practice and are to be provided by other specialists of the Client's choice. However, they may be included in the inspection as part of Optional Fee Based Services as outlined in 266 CMR 6.07. |
| | Fee Paid Inspection. A Home Inspection carried out in accordance with 266 CMR 6.04 for |
| | which the Client pays a fee and receives a Report. |
| | Eccder. All circuit conductors between the service equipment, the source of a separately derived system, or other power supply source and the final branch-circuit overcurrent device. |
| | Eully Depreciated. Item/System inspected is no longer under the manufacturer's warranty and |
| | it is reaching the end of its serviceable life. The Item/System/Component has no dollar or salvage value, and replacement should be anticipated. |
| | Functional Drainage. A drain is functional when it empties in a reasonable amount of time and does not overflow when another fixture is drained simultaneously. |
| | Functional Flow. A reasonable flow at the highest fixture in a dwelling when another fixture is |
| | operated simultaneously. |
| | Heating Services. As defined in M.G.L. c. 148, §§ 10C and 10H, and 527 CMR 4.00: Oil Burning Equipment, plumber and electrician license required where applicable). |
| | |
| 1/25/08 | 266 CMR - 6 |
| | · |
| | |
| | |

| SUMMARY ROOFING EXTERIO | R STRUCTURE ELECTRICAL HEATING INSULATION PLUMBING | INTERIOR SITE IN |
|-------------------------|--|------------------|
| PPENDIX REFERENCE | | |
| | | |
| | | |
| | | |
| | 266 CMR: BOARD OF REGISTRATION OF HOME INSPECTORS | |
| 2.0 | 11: continued | |
| | <u>Home Inspection</u> . The process by which an Inspector, pursuant to the sale and transfer of a residential building, Observes and Reports On those systems and components listed in 266 CMR 6.00 <i>et seq</i> with the exception of the noted exclusions and prohibitions. | |
| | Home Inspector. A person licensed pursuant to M.G.L. c. 112, § 222. | |
| | Household Appliances. Kitchen and laundry appliances, room air conditioners, and similar appliances. | |
| | Identify. To name. | |
| | Indirect Supervision. The oversight of activities, other than direct observation, performed by the Supervisor in order to provide guidance to the Associate Home Inspector. These activities may include meeting with the supervisee; reviewing Reports prepared by the supervisee; reviewing and evaluating the supervisee's activities in connection with home inspections; and having supervisory conferences that may be conducted by telephone. | |
| | In Need of Repair. Does not adequately function or perform as intended and/or presents a Safety Hazard. | |
| | Installed. Attached or connected such that the installed item requires tools for removal. | |
| | Inspect/Inspected. To Observe the Readily Accessible systems or components as required by 266 CMR 6.04 et seq. | |
| | Inspector. A person licensed under M.G.L. c. 112, § 222 or 223. | |
| | Interior Wiring. Includes the exposed and Readily Observable Peeder and Branch Circuit wiring in the dweiling. | |
| | Mock Inspection. A simulated home inspection carried out for training purposes only and there is no Client involved. | |
| | Normal Operating Controls. Homeowner Operated devices such as a thermostat or wall switches. | |
| | Note. Record in the Report. | |
| | Observable. Able to be observed at the time of the inspection without the removal of fixed or finished coverings and/or stored materials. | |
| | Observe. The act of making a visual examination. | |
| | <u>On-site Water Supply Ouality</u> . The condition of the potable water based on an evaluation of its bacterial, chemical, mineral, and solids content. | |
| | On site Water Supply Quantity. The volume of water available measured over a period of time. | |
| | Operate. To cause systems or equipment to function. | |
| | Optional Services. Optional fee based services, which are beyond the scope of the Home Inspection as defined by 266 CMR 6.00 et seq. | |
| | Plumbing Services. As defined in M.G.L. c. 142 and 248 CMR 2.04 (plumber license required) | |
| | Primary Windows and Doors. Windows and exterior doors that are designed to remain in their respective openings year round. | |
| | | |
| | | |
| 1/25/ | 08 266 CMR - 7 | |
| | | |
| | | |
| | | |
| | | |

| 127 Jackson Way, Northampton, | | | |
|---------------------------------------|--|----------|-------------|
| | R STRUCTURE ELECTRICAL HEATING INSULATION PLUMBING | INTERIOR | SITE INFO |
| APPENDIX REFERENCE | | | |
| | | | |
| | | | |
| | 766 CMD. BOADD OF DESIGN AWAY OF TOUR DISDECTOR | | |
| | 266 CMR: BOARD OF REGISTRATION OF HOME INSPECTORS | | |
| 2.01: | Continued | ~ | |
| | <u>Readily Accessible</u> . Capable of being reached quickly for visual inspection without requiring the Inspector to climb over or remove any personal property, to dismantle, to use destructive measures, to resort to portable ladders and/or any action which will likely involve risk to persons or property. | | |
| | <u>Readily Operable Access Panel</u> . A panel provided for homeowner inspection and maintenance, which has removable or operable fasteners or latch devices in order to be lifted, swung open, or otherwise removed by one person, and its edges and fasteners are not painted in place. (The panel must be within normal reach and not blocked by stored items, furniture or building | | |
| | components.) <u>Readily Observable Signs</u> . Conditions of deterioration on the surface including, but not limited to: water stains, wood destroying fungi, insect infestation and deterioration suggesting the | | |
| | potential for concealed damage. <u>Recreational Facilities</u> . Whirlpools, saunas, steam baths, swimming pools, tennis courts, playground equipment, and other entertainment or athletic facilities. | | |
| • | <u>Registered Professional Home Inspector</u> . A Registrant (person) licensed pursuant to M.G.L. c. 112, § 222, by the Division of Professional Licensure. | | |
| | Registrant. "Register", "Registered", "Registrant", and "registration" shall be used interchangeably with the words "license", "licensed", "licensee", and "licensure". | | |
| · · · · · · · · · · · · · · · · · · · | <u>Repair</u> . All repairs, when implemented by the buyer, seller, and/or homeowner shall comply with applicable requirements of the governing codes and sound construction practices. | | |
| | <u>Report</u> . A written document setting forth findings of the Home Inspection unless otherwise specified in 266 CMR 2.00. | | |
| | <u>Report On</u> . A written description of the condition of the systems and components observed. (The Inspector must state in his or her Report whether the System or Component has Readily Observable Signs indicating that it is need of repair or requires further investigation. | | |
| | Representative Number. For multiple identical components such as windows, doors and electrical outlets, etc. one such component per room. | | |
| | Residential Building. A structure consisting of one to four dwelling units under one roof. | | |
| | Roof Drainage Systems. Gutters, downspouts, leaders, splash blocks, and similar components used to carry water off a roof and away from a dwelling or residential building. | | |
| | Safe Access. Access free of any encumbrances, bazardous materials, health and Safety Hazards such as climbing and/or standing on anything other than the ground and/or floor which may jeopardize the Inspector as determined by the Inspector. | | |
| | Safety Glazing. Tempered glass, laminated glass, or rigid plastic. | | |
| | <u>Safety Hazard</u> . A condition in a Readily Accessible, installed system or component, which is judged by the Inspector to be unsafe, or of significant risk of personal injury during normal day- to-day use. (The risk may be due to damage, deterioration, improper installation or a change in the accepted residential construction standards.) | | |
| | Seller/Seller's <u>Representative</u> . The owner of the property or one legally authorized to act on behalf of the owner such as an administrator, executor, guardian, or trustee, whether or not a natural person or Agent representing the seller. | | |
| | <u>Shut Down</u> . A piece of equipment or a system is shut down when the device or control cannot be Operated in a manner that a homeowner should normally use to Operate it. (Inspectors are prohibited from operating the equipment or system). | | |
| 1/25/08 | 266 CMR • 8 | | |
| | | | |
| | | | |
| | | | |
| | Setting the standard for quality home inspections. | Paç | ge 51 of 58 |

127 Jackson Way, Northampton, MA March 20, 2015

| IMMARY ROOFING EXTERIOR | STRUCTURE ELECTRICAL HEATING INSULATION PLUMBING INTERIOR | SITE INF |
|-------------------------|--|----------|
| PENDIX REFERENCE | | |
| | | |
| | | |
| | | |
| | 266 CMR: BOARD OF REGISTRATION OF HOME INSPECTORS | |
| 2.01 | | |
| | continued | |
| | <u>Solid Fuel Heating Device</u> . Any wood, coal, or other similar organic fuel-burning device including, but not limited to, fireplaces (whether masonry or factory built), fireplace inserts, stoves, central furnaces, and any combination of these devices. | |
| | Structural Component. A component that supports non-variable forces or weights (dead loads) and variable forces or weights (live loads). | |
| | Sufficient Lighting. Fully lighted with a minimum of 50-lumens in all areas to be inspected. | |
| | Supervisor. The licensed Home Inspector designated to oversee and supervise the training of an Associate Home Inspector and/or Trainee. | |
| | System. A combination of interacting or interdependent components assembled to carry out one or more functions. | |
| 4 | Technically Exhaustive. An inspection is technically exhaustive when it involves the use of measurements, instruments, testing, calculations, and other means to develop scientific or engineering findings, conclusions, and recommendations. | |
| | <u>Traince</u> . A person in the Associate Home Inspector Training Program for the purpose of meeting the requirements of M.G.L. c. 112, § 223 to qualify for licensure as an Associate Home Inspector. | |
| | Under Floor Crawl Space. The under-floor space between the bottom of the floor joists and the earth or floor under any Dwelling and/or Residential Building. | |
| REGU | LATORY AUTHORITY | |
| | 266 CMR 2.00: M.G.L. c. 13, § 96 and M.G.L. c. 112, §§ 221 through 226. | |
| | | |
| | | |
| | · · · · · · · · · · · · · · · · · · · | |
| | | |
| · · · | | |
| : · · · · · | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| 5 S | | |
| | | |
| | · | |
| | | |
| | | |
| 1/25/08 | 266 (2) (2) | |
| | 266 CMR - 9 | |
| | | |
| | | |
| | | |

Setting the standard for quality home inspections.

Page 52 of 58

| MMARY ROOFING I | EXTERIOR STRUCTURE | E ELECTRICAL H | EATING INSULAT | ION PLUMBING | INTERIOR | SITE IN |
|-----------------|--------------------|-----------------------|---------------------|--------------|----------|---------|
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | : BOARD OF REGISTRATI | ON OF HOME INSPECTO | RS | | |
| | NON-TEXT PAGE | | | · | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | · | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| ÷ | | | | | | |
| | | | | | | |
| | . ' | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | 1/25/08 | | A// A | 10 | | |
| | | | 266 CMR | - 10 | | |
| | | | | | | |
| | | | | | | |

127 Jackson Way, Northampton, MA March 20, 2015

| IZI Jacka | son way, Non | inampton, w | | .0, 2013 | | | | | |
|-----------|--------------|-------------|-----------|------------|-----------|---------------|-----------|----------|-----------|
| SUMMARY | ROOFING | EXTERIOR | STRUCTURE | ELECTRICAL | HEATING | INSULATION | PLUMBING | INTERIOR | SITE INFO |
| APPENDIX | REFERENCE | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | <u>R</u> | EQUIRED H | ANDOUT PU | RSUANT TO |) 266 CMR 6.0 | <u>08</u> | | |
| | | | | | | | | | |
| | | | | | | | | | |

Pursuant to M.G.L. c. 13, s. 97A, and 266 CMR 6.08 Home Inspectors and Associate Home Inspectors are required to provide a document outlining the procedures and benefits of a home energy audit to all Clients purchasing a single-family residential dwelling, a multiple-family residential dwelling with less than 5 dwelling units or a condominium unit in structure with less than 5 dwelling units.

CONCERNED ABOUT RISING ENERGY COSTS? MASSSAVE CAN HELP.

There are so many great reasons to make energy-saving changes to your home—reduced energy costs throughout the year, improved home comfort, and lower greenhouse gas emissions.

- MassSave may provide you a no-cost home energy assessment to identify the energysaving improvements that are right for you.
- MassSave may provide money toward the cost of purchasing and installing approved energy-saving measures and money-saving rebates when you install qualifying energy efficient equipment.

Get started today. Call MassSAVE at 866-527-7283 or go to www.masssave.com for more information or to schedule your home energy audit.

| X av North | ampton, MA March 20, 2015 | Report |
|----------------------|---|----------|
| OFING | EXTERIOR STRUCTURE ELECTRICAL HEATING INSULATION PLUMBING | INTERIO |
| RENCE | | |
| | | |
| | | |
| | | |
| mport | ant Questions for the Seller/Seller's Representative | |
| fo the Bes | t of Your Knowledge as the Seller and/or Seller's Representative: | |
| | Does the dwelling have a history of seepage, dampness, and/or water penetration into the 'or Under Floor Crawl Space? If so please explain. | Basement |
| (b) | Has a sump pump ever been installed or used in the Basement/Under Floor Crawl Space? | |
| (c) | Do you use any type of dehumidification in any part of the dwelling? | |
| (d) | Are you aware of any mold and/or air quality issues in the dwelling? | |
| (e) | Is the dwelling on a private sewage system? | |
| | 1. If the waste system is private, has a Title V inspection been completed, and is the o Title V Report available for review? | ompleted |
| | 2. Has the dwelling ever been inspected and/or treated for insect infestation? | |
| | a. If so, when? | |
| | b. What were the chemicals used? | |
| (f) | Has the dwelling ever been tested for radon gas and/or lead paint? | |
| | 1. If so when? | |
| | 2. What were the results? | |
| (g) | Has the dwelling ever been inspected by an Inspector? | |
| | 1. If so, when? | |
| | 2. Were any problems noted? | |
| | 3. Is a copy of the inspection Report available? | |
| | Are the Seller/ Seller's Representative aware of any structural, mechanical, electrical or or erial defects that may exist on the property? | ther |
| (i) | Has there ever been a fire in the dwelling? | |
| | 1. If so, when? | |
| | 2. What areas were involved? | |
| | 3. What chemical cleaners, if any, were used for cleanup? | |
| (j) | Has there ever been a hazardous waste spill on the property? | |
| (k) | Is there is an underground storage tank on the property? | |
| | | |
| | | |
| | | |
| | | |

Setting the standard for quality home inspections.

Page 55 of 58

127 Jackson Way, Northampton, MA March 20, 2015

| SUMMARY ROOFING EXTERIOR STRUCTURE ELECTRICAL HEATING INSULATION PLUMBING INTERIOR SITE INFO |
|--|
| APPENDIX REFERENCE |
| |
| |
| |
| List of tradespeople you might want to call |
| |
| Roofing: RCI Roofing, LLP 413 527 4775 |
| Sexton Roofing and Siding Company: 413 534 1234 |
| Hawkins Roofing Services, slate and roof repair. 413 774 6834 |
| Jack Morse and Son Roofing 413 634 8035 |
| General Contractors: Construct Associates, Inc. 413 584 1224 |
| Wright Builders, Inc. 413 586 8287 |
| W. Marek Inc. 413 527 7667 (will also do roofing) |
| Sarafin Builders: 413 527 7812 |
| Sackrey Construction, LLC 413 665 9995 |
| Smaller Contractors/carpenters: (These guys may also do roofing) |
| Richard Nelson 413 268 9335 |
| Richard LaBombard 413 527 7427 |
| Tom Dolan 413 296 4303 |
| Electrical work: Blanchard and Daly 413 527 1234 |
| Curt Golec 413 320 1156 |
| Marney Electrical Services Inc. 413 584 0737 |
| Whiteley Elictric 413 527 1440 |
| Plumbing, Heating, HVAC: Walunas Plumbing and Heating 413 529 2675 |
| Orchard Valley Heating and Cooling 413 527 5812 |
| Hodge City Mechanical 413 586 1150 |
| Rich Strong Air Conditioning 413 247 0095 |
| Richards Plumbing and Heating 413 527 0291 |
| Fuel and Heating: Richards Fuel and Heating Inc. 413 527 0194 (oil) |
| Cernak Fuel 413 527 4840 (oil, tank removal) |
| George Propane Inc. 413 268 8360 |
| Oil Tank Inspections: Fuel Services, 413 315 5391 |
| Rice Energy, 800 776 7263 |
| Insulation: Cozy Home Performance 413 529 0200 |
| First Prize spray foam insulation 413 203 5160 |
| |
| |
| |
| |

Setting the standard for quality home inspections.

| SUMMARY | ROOFING | EXTERIOR | STRUCTURE | ELECTRICAL | HEATING | INSULATION | PLUMBING | INTERIOR | SITE INFO | |
|--|---|-------------|----------------------------------|------------|---------|------------------|----------|----------|-----------|--|
| APPENDIX | REFERENCE | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| Gutters and Downspouts: Mr Gutter 413 586 7451 (also does metal roofing) | | | | | | | | | | |
| Flooring: Wagner Rug and Flooring 413 568 0520 | | | | | | | | | | |
| | Floor refinishing: Dion and Son 413 584 6170 | | | | | | | | | |
| Ceramic Tile: Mike McKenna 413 527 1266 | | | | | | | | | | |
| | Masor | ny: Mike Mc | (enna <i>1</i> 1352 [.] | 7 1 2 6 6 | | | | | | |
| | Masonry: Mike McKenna 413 527 1266 Chimney Cleaning and Masonry: The Superior Chimney sweep 413 529 9436 | | | | | | | | | |
| | | | | - , | | / I ^z | | | | |
| | | | | | | | | | | |

REFERENCE LIBRARY

| SUMMAR | RY ROOFING | EXTERIOR | STRUCTURE | ELECTRICAL | HEATING | INSULATION | PLUMBING | INTERIOR | SITE INFO | | |
|---|------------------------|-------------|-------------|----------------|---------|------------|----------|-----------------|-------------------|--|--|
| APPEND | IX REFERENCE | 1 | | | | | | | | | |
| The links below connect you to a series of documents that will help you understand your home and how it works. These are in addition to links attached to specific items in the report. | | | | | | | | | | | |
| Click on any link to read about that system. | | | | | | | | | | | |
| >> | 01. ROOF | ING, FL/ | SHINGS | AND CH | IMNEYS | \$ | | | | | |
| >> | 02. EXTER | RIOR | | | | | | | | | |
| >>> | 03. STRUCTURE | | | | | | | | | | |
| \bigcirc | 04. ELECTRICAL | | | | | | | | | | |
| >>> | 05. HEATING | | | | | | | | | | |
| >> | 06. COOLING/HEAT PUMPS | | | | | | | | | | |
| >> | 07. INSUL | ATION | | | | | | | | | |
| \bigcirc | 08. PLUM | BING | | | | | | | | | |
| \bigcirc | 09. INTERIOR | | | | | | | | | | |
| >> | 10. APPLI | ANCES | | | | | | | | | |
| \bigcirc | 11. LIFE C | YCLES | AND COS | STS | | | | | | | |
| \bigcirc | 12. SUPPI | LEMENT | ARY | | | | | | | | |
| | Asbesto | S | | | | | | | | | |
| | Radon | | | | | | | | | | |
| | Urea Fo Lead | rmaldehyde | ∋ Foam Insu | lation (UFFI) |) | | | | | | |
| | | Monoxide | | | | | | | | | |
| | Mold | | | (han) | | Anne | | | | | |
| | Househo | old Pests | | C I P | | | | | | | |
| | Termites | s and Carpe | enter Ants | Contraction of | | F | - Second | | | | |
| \bigcirc | 13. HOME | SET-UF | AND MA | | NCE | | | | | | |
| \bigcirc | 14. MORE | | | | ONS | | | | * | | |
| | | | | | | - | | 1 | and the second of | | |
| | | | | | | A. | - | The Property is | | | |